



Release Notes:

ProCurve Mobility Manager Version 1.1, Update 1

Installation Pre-Requisites

ProCurve Mobility Manager 1.1 (PMM 1.1) Update 1 requires that you have the following software installed and configured on your systems:

- ProCurve Manager Plus (PCM+) version 2.2/2.2.1, with Update 4 installed.
- ProCurve Mobility Manager 1.1

These release notes include information on the following:

- A listing of software fixes included in the Auto-Update releases. ([Page 4](#))
- A listing of Known Issues. ([Page 5](#))

Related Publications

For the latest version of any of the publications listed below, visit the ProCurve Networking Web site at <http://www.procurve.com>. Click on **Technical support**, then **Product manuals**.

- Read Me First for the ProCurve Manager, Version 2.2
- ProCurve Network Management Getting Started Guide
- ProCurve Manager Plus 2.2 Network Administrator's Guide

© Copyright 2005 - 2007
Hewlett-Packard Development Company, LP.
The information contained herein is subject to change
without notice.

Publication Number

5991-4779
September, 2007

Applicable Products

- J8990A - ProCurve Mobility Manager 1.0

Trademark Credits

Microsoft®, Windows®, and Windows NT® are US registered trademarks of Microsoft Corporation. Adobe® and Acrobat® are trademarks of Adobe Systems Incorporated. Java™ is a US trademark of Sun Microsystems, Inc.

Software Credits

SSH on ProCurve Switches is based on the OpenSSH software toolkit. This product includes software developed by the OpenSSH Project for use in the OpenSSH Toolkit. For more information on OpenSSH, visit

[http:// www.openssh.com](http://www.openssh.com).

SSL on ProCurve Switches is based on the OpenSSL software toolkit. This product includes software developed by the OpenSSL Project for use in the OpenSSL Toolkit. For more information on OpenSSL, visit

<http://www.openssl.org>.

This product includes cryptographic software written by Eric Young (eay@cryptsoft.com). This product includes software written by Tim Hudson (tjh@cryptsoft.com)

Disclaimer

HEWLETT-PACKARD COMPANY MAKES NO WARRANTY OF ANY KIND WITH REGARD TO THIS MATERIAL, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. Hewlett-Packard shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Hewlett-Packard assumes no responsibility for the use or reliability of its software on equipment that is not furnished by Hewlett-Packard.

Warranty

See the Customer Support/Warranty booklet included with the product.

A copy of the specific warranty terms applicable to your Hewlett-Packard products and replacement parts can be obtained from your HP Sales and Service Office or authorized dealer.



Hewlett-Packard Company
8000 Foothills Boulevard, m/s 5551
Roseville, California 95747-5551
www.procurve.com

Software Management – PMM 1.1 Update 1

If upgrading from ProCurve Manager 2.2, ProCurve Manager 2.2 Update 1 must be manually installed before installing this ProCurve Mobility Manager 1.1 update. Once you have installed the ProCurve Manager 2.2 update, you can install this update using the “Automatic Update” feature in PCM+, or you can install it manually.

To verify if the Update has already been installed, look in the Update History window under the PCM Global Preferences:

[Tools->Preferences->Automatic Updates->Update History]

Using the PCM Automatic Update to Install

1. Open the Preferences panel in the PCM Client and select the **Automatic Updates** node.
2. Click the **Check Now** button. A dialog appears with a list of the available update(s).
3. Select the update, ensure that the **install** checkbox is enabled and click the **Next** button.
4. A warning message appears, advising you that any PCM clients will be disconnected. Click **OK** to continue.
5. After the update package is downloaded, you will be prompted to close the PCM Client. Click **OK** to close the pop-up, then close the Preferences window and exit PCM.

The update will be applied and the PCM services restarted. Once this is done you can reconnect with the PCM client and begin using the updated version of Network Immunity Manager.

Using the Manual Process to Install

1. Copy the pmm_1_1_update_1.zip file to the \PNM\server\data\download\autoupdate directory. (Do not unzip the file.)*
2. Open the Preferences panel in the PCM Client and select the **Automatic Updates** node to display the Global:Automatic Updates panel.
3. Click the **Check Now** button at the bottom of the panel to display the **Select update mode:** dialog.
4. Select the **Check for updates in PCM's download folder** option and press **Next**.
5. You should see the new auto-update presented for installation, and you can continue with the Update installation (steps 3 through 5 above).
6. Restart the client and verify that the update was applied by checking the **Update History** node located under the Automatic Updates preference node.

* The default PCM server installation directory is: C:\Program Files\Hewlett-Packard\PNM\server on the workstation where PCM was initially installed.

Software Fixes in PMM 1.1 Update 1

The following Mobility Manager 1.1 problems were resolved in Mobility Manager Update 1:

- **Wireless Edge Services zl Module (PR_1000448012)** — Support for ProCurve Wireless Edge Services zl Module.
- **Passive Scanning (PR_1000414850)** — Add a per-radio box check for passive (single channel) scanning.
- **Power Settings (PR_1000442094)** — Convert transmit power settings for WESM xl and WESM zl to dBm.

Known Issues for PMM 1.1 Update 1

- (PR_1000458353) — Existing WESM zl devices discovered remain in the “ProCurve Others” navigation tree folder after PMM 1.1 AU1 is installed. The workaround is to restart the PCM client.
- (PR_1000460189) — RADIUS-authenticated clients from an AP 530 may not be displayed in the Stations table.
- (PR_1000462039) — Radio Ports tab incorrectly reports MAC address in the Radio Port serial number column.