Firmware Release Note

Model: M5370 Series Date: 28-Dec-2019

V5.H6.01 FW addresses total of 3 issues.

- Major Changes
- 1) Removed the functionality to print the barcode.
- 2) Fixed, the SNMP OID status for HCF tray to display it on the panel.
- 3) Applied the new WLED for Scanner.

Please upgrade the FW with V5.H6.01 if any one of the mentioned problems need to be resolved.

| Version | Category | TSP ID | Division | Change Description |
|--------------|----------|--------|----------|---|
| | Problem | | KOREA | Removed the functionality to print the barcode. |
| V5.H6.01 | Problem | | KOREA | Applied the new WLED for Scanner. |
| (2019-12-28) | Problem | | KOREA | Fixed, the SNMP OID status for HCF tray to display it on the panel. |

Software Component Versions

| System Firmware | V5.H6.01 |
|-----------------------|----------------------------|
| Main FW Version | V11.01.13.00_09-20-2019 |
| XOA Web | 1.4.33 |
| UP | 1.17.34_(20171218171009) |
| Engine Firmware | V1.00.31 |
| File System Version | FS_V14.03.06.17.13 |
| SCB(Scan,Fax) Version | V3.00.04.06 12-02-2019 |
| Boot Rom Version | V13.10.00.00.92-04-08-2019 |
| UI Firmware | V5.18.50.12.00_19040115 |
| ADF Firmware | 01.30.16 |
| Tray1 | V1.00.31 |
| Tray2 | V3.1.9 |
| Tray3 | V3.1.9 |
| finisher Version | V5.05 |
| PCL5CE | V8.22_170906 |
| PCLXL | V11.00.87 |
| PS/PDF/XPS | V6.21.01.62.02.03_170415 |

Image Quality Tables

| image Quanty Tubics | |
|---------------------|-------------|
| EP | V2.29 |
| Fuser | V2.90 |
| Toner | V2.08 |
| TR | V1.41 |
| Print CMS | V2.1.0430 |
| Copy CMS | V2.5.190107 |
| Scan CMS | V1.33 |
| Print IEM | V1.00 |
| Copy IEM | V2.7RX2 |

Update dependency

If the previous firmware version is lower than V5.C6.03, please install Service Pack first, which is needed to prevent delay in upgrading all UI firmware

Solution Compatibility Table (M5370 : V5.H6.01)

| Category | Solution Name | Solution Version | | Verified F/W Version |
|----------|----------------------|------------------|---|-------------------------|
| | CloudConnectorCore | 2.50.008 | 0 | |
| | DocumentWorkflowCore | 2.50.007 | 0 | |
| BCPS | PrintingSecurityCore | 2.50.009 | 0 | |
| BCFS | SecureLoginCore | 2.50.006 | 0 | |

| | UsageTrackerCore | 2.50.007 | 0 | |
|-----------|------------------------------|---|---|--------------------|
| | XOA-WEB Enabler | 2.00.003 | 0 | V5.D6.04 |
| | Autostore | 1.0.0 (Server : 7.00.3.0 (DRS:7.0.1.16, APD:7.0.3.26)) | 0 | V5.E6.04.02.060911 |
| | Drivve Image | 1.5.43 (Server : 5.1.546) | 0 | V5.C6.05 |
| | Drivve Print | 1.1.30 (Server : 3.1.100) | 0 | V5.C6.05 |
| | Equitrac | 1.1.0.135 (Server : 5.2.21.8778) | 0 | V5.D6.15.03.120609 |
| | Geniusbytes MyMFP | 2.19.6.2 (Server : 2.19.3) | 0 | V5.G6.01.02.050715 |
| | NDDigital n-Access | 2.1.3 (Server : NDDigital n-Billing 4.9) | 0 | V5.D6.04 |
| | NDDigital n-Collector | 2.2.4 (Server : NDDigital n-Billing 4.9) | 0 | V5.D6.04 |
| | NDDigital n-Releaser | 2.1.4 (Server : NDDigital n-Billing 4.9) | 0 | V5.D6.04 |
| | Omtool AccuRoute | 1.0.0.689 (Server : 2013(Build 5)) | 0 | V5.D6.04 |
| ISV-XOA-E | PaperCut | 1.1.0 (Server : 16.4 (build 38954)) | 0 | V5.F6.01 |
| | PrintFleet Cloud Embedded DC | 1.1.249 (Server : 3.6) | 0 | V5.E6.04.02.060911 |
| | Ringdale FollowMe | 1.1.2.9 (Server : 6.1.0.103) | 0 | V5.D6.04 |
| | SafeCom | 010.24.23 (Server : 10.520.10.35) | 0 | V5.F6.04.03.092016 |
| | SafeQ Embedded Terminal | 1.0.0 (Server : C.0.18.002) | 0 | V5.D6.15.03.120609 |
| | Scanner Vision | 1.0.6 (Server : 6.2.0.270) | 0 | V5.D6.04 |
| | Scanshare Essentials | 1.5.15.167 (Server : 4.0.5) | 0 | V5.D6.04 |
| | Ubiquitech Easy & VDMS | 1.5.3-rel3 (Server : 5.0.0-rel [ca91b]) | 0 | V5.D6.15.03.120609 |
| | e-Paper Sentinel | 5.0.7 | 0 | V5.D6.04 |
| | Prism ScanPathTM | 1.0.49 (Server : 2.5.0.29) | 0 | V5.C6.05 |
| SmartUX | Nuance unified client | 1.0.0.606 (Server : 5.7.28.6490(CAS:5.7.28.6490, APD : 7.0.4.0)) | 0 | |
| PrinterOn | PrinterOn Branded Agent | 2.03.003 | 0 | V5.F6.04.03.092016 |

FW Release History

| Version | Category | TSP ID | Division | Change Description |
|--|-------------|----------------------|----------|---|
| | Problem | | KOREA | Fixed, XSS weak point of Samsung models. |
| | Problem | | KOREA | Fixed, slow UI and slow copy feature. |
| | Problem | | KOREA | Fixed, IPv6 manual address for fdxx as prefix. |
| | Problem | | KOREA | Fixed, MP Holder Pad to display in SWS. |
| | Problem | | KOREA | Fixed, S5-3116 if no hardware failure. |
| V5.G6.01.02. | Problem | | KOREA | Implementation of new requirement to enhance the SWS security. |
| 050715 | Problem | | KOREA | Fixed the IDCopy parameter getting reversed while submitting of job. |
| (2019-05-30) | Problem | | KOREA | Fixed, to print all documents in queue from BCPS when documents come from MacOS. |
| | Problem | | KOREA | Fixed, the fax not working while in power save mode. |
| | Problem | | KOREA | Fixed the issue of device going to home screen after login using GeniusMFP solution. |
| | Problem | | KOREA | Fixed, Manual Reset of device quota reset policy. |
| | Problem | | KOREA | Fixed, android security issue for password field. |
| V5.G6.01 (2019-01-30) | Problem | | KOREA | Fixed the UI slowness issue which use to happen after adding more widgets at home and mahcine was not rebooted for 2 to 3 days. |
| | Problem | | KOREA | Fixed the issue that image log not sent to Printing Security Solution Server when fax images recieved through Line2 |
| | Problem | | DEV | Fixed the issue of WSD Print installation with Win10 (1703/1709/1803) |
| V5.F6.04.03.0 92016 (2018-11-01) | Problem | | DEV | Fixed the Google Address Book stay signin issue and showing previous user contacts |
| (2000 10 00) | Problem | SIE174695 | EMEA | Fixed the issue of Box app Athentication |
| | Problem | | DEV | Fixed MFP slow down issue with mDNS |
| | Problem | SIP68753 TP174000 | EMEA | S1-2452 Error issue was fixed by improving the DB recovery logic |
| | Problem | | DEV | When SNMP Community Web Service is called via HPSM application to add/edit/delete the community names, a side effect is observed that SNMPv3 is getting disabled. This side effect is fixed |
| V5.F6.04.02.0 71215 (2018-08-01) | Problem | SIP68582 | AMS | Fixed SMB 2/3 job failed issue due to excessive permissions requested |
| (2010-00-01) | Requirement | | DEV | SNI(Server Name Indication) is added by new requirement for Google Cloud Print servers when SSL enabled. |

A solution has been verified and MUST be compatible with the releasing F/W version.
 Previously the supported solutions have been tested and verified with the version specified in the "Verified F/W version" row in the table.
 The required test has been conducted on this FW version to ensure the backward compatibility with "Verified F/W version".

| | Requirement | | DEV | New feature implementation for configurable 'SSL/TLS' protocols and ciphers option. Security level configuration can be done according to user requirement from SWS. |
|------------------------------|-------------|------------------------|-------|---|
| | Problem | TP1790KD | SEAU | 'Error 403' caused when connecting to Google Addressbook due to Google policy changes is fixed. |
| | Problem | - | DEV | The intermittent stoppage caused when creating Hibernation Image when https is enabled is fixed. |
| | Problem | - | DEV | Inaccurate range value associated with Scan background density from Nuance Unified client compatibility test is fixed. |
| W. T. C. O. A. O. A. O. | Problem | TP17A06W | SEA | The issue that file stored at Box App is not intermittently deleted at the device where HDD Image Overwrite is enabled is fixed. |
| V5.F6.04.01.0 41619 | Problem | - | SEBN | Login speed has improved when using Nuance Unified client. |
| (2019 05 04) | Problem | SIP65701 | SEG | The issue that certificate related setting value is reset as default after changed F/W version including updated Send App is installed is fixed. |
| | Problem | SIP64544 | SEAU | The issue that fuser detection fails due to intermittent timing in case that a user sends a job when the device enters sleep is fixed. |
| | Problem | SIE154757 SIE156425 | SAU | The issue that email is not delivered under ScantoEmail in case that special characters(ex) ',') are included in sender's user name is fixed. |
| | Requirement | SIE157066 | EMEA | New certificate of Google Cloud server is applied. |
| | Problem | - | SEG | Copy sharpness value change failure on FAP is fixed. |
| | Problem | <u>-</u> | EMEA | Special characters except for '<' and '>' are now allowed as LDAP server access password. |
| V5.F6.04 (2018-02-12) | Problem | - | KOR | Change to define start and end time when enabling performance optimization feature. |
| | Problem | - | SEG | Fixed an issue of unintended color being printed because of wrong processing of 1x1 size pattern in PCL5 job for color printers. |
| | Problem | - | KOR | Fixed an issue of black text printed as white in specific application for color printers. |
| V5.F6.01 | 5 11 | | | Fixed an issue of the reset database menu being displayed at booting phase by intermittent |
| (2017-10-27) | | TP17801L | SEBN | corruption of audit database index. LUI default screen is changed to Kiosk home screen when FDI and Smart Printing Kiosk app are |
| | Requirement | - | SEF | used together. |
| | Problem | TP1720J901 | KOR | Allow Korean characters in the Scan to SMB path. |
| | Problem | - | DEV | Fixed an issue of iterated login and logout when performing NFC authentication on device, WIFI/NFC module(SL-NEW001X) installed, with the latest cellular phones such as Galaxy S8. |
| | Problem | TP1740C3 | SEA | Fixed an issue of slow booting or WIFI disconnection when power cycled by soft power button on UI when WIFI/Bluetooth (BLE, Bluetooth Low Energy) module(SL-NWE002X) installed. |
| | Problem | TP1740O0 | SEUK | Improve DB(Database) error recovery routine for damaged record only instead of DB initialization. |
| 90110 | Problem | TP176005 | SEI | Fixed an issue of the memory clear button in the service menu not being activated after power on but intermittent exception occurred in WSD initialization. |
| (2017-09-20) | Problem | TP1750OA | SEG | Allow compact PDF option in XOA-E API for ISV solutions. |
| | Requirement | - | DEV | The Blue Angel 2017 ready. |
| | Problem | TP17704P | SEG | Fixed an issue of WIFI direct not being connected when WIFI/Bluetooth module(SL-NWE002X) installed with 802.11ac mode in MX4 model. |
| | Problem | - | DEV | Fixed an issue of a fuser replacement message not disappearing even though turning off fuser replacement alarm. |
| | Problem | TP177025 | SEHK | Fixed an issue of a Fax Rx job pending when all received pages can not be decoded by corrupted data. |
| | Problem | TP16C0JD | SEIL | Fixed an issue that the destination of Scan Widget was displayed as None after the Scan Widget was terminated abnormally. |
| | Requirement | TP1710KL | SEASA | A new API was provided to hide buttons on the navigation bar of UI such as back/home button. |
| | Requirement | TP1730AG | SEPOL | Remove destination email address in the PDF file generated from Scan to email. |
| | Problem | TP1710JX | SEG | Fixed an issue where one of continous printing jobs was not printed intermittently due to problems while spooling data to HDD. |
| V5.E6.04.02.0 | Problem | TP1670LC | SEA | Added a new settings which specifies a default folders of Box App. * Box App > Action Overflow(3 dot button) > Box Settigns > Default Display Folder |
| 60911 (2017-06-20) | Problem | - | DEV | Fixed an issue that sometimes a job was not canceled and remained cancelling state until rebooting. |
| | Problem | TP1740DR | SEUK | Fixed an issue that when a large number of print jobs were saved in the Box, some of jobs were not printed by Print & Delete function for all jobs. |
| | Problem | TP1750CC | SEG | Fixed an issue of stripped patterns on the part of image of PCL5 job which consists of mono data and color macro data. |
| | Problem | TP17600R | SEG | Fixed an issue where finishing option is cleared to default when the job was rescheduled by paper mismatch/empty. |

| Requirement P16A0SB SEUK Added a Jam Count Reset feature to the service mode. Added a Jam Count Reset feature to the service mode. Added a Jam Count Reset feature to the service mode. Added a reset button to Service Mema & Maintenance Counts > Jam Count menu Problem P16A0SB SEG Fised an issue where the separator page was stapled together with the original printout Separator Page was capilled to the PC driver. Problem P16COIQ SEA Populate recipient name in front of "From" email address at the Scan to email function exc.) As-ls : from : cogh@@pl.com> To-Be : From : "ght@@pl.com> The delivery in the LDAP search option. As-ls : Test_DOMOTY single every single page for multiple printing of one page. SECH Problem P1916OBG SECH Steel Supported a special character V in the LDAP search option. Added a finicin to nationatically fluster email address eigstsred in the job account of recipients when logging in and running Scan & Scan Options > Filename, real time will be used if it still has Dates&Time format, such as DDMMYY. As-ls : test_DDMMYY saved as "test_DDMMYY" To-Be: test_DDMMYY saved as "test_DDMMYY" To-Be: test_DDMMYY will save as "test_DDMMYY" To-Be: test_DDMMYY will save as "test_DDMMYY" To-Be: test_DDMMYY saved as "test_DDMMYY" To-Be: test_DDMMYY saved as "test_DDMMYY" To-Be: test_DDMMYY saved as "test_DDMMYY" To-Be: test_DDMMYY will save as "test_DDMMYY" To-Be: test_DDMMYY saved as "tes | | | | | Added Bates Numbering feature to the copy app. |
|--|----------------|-------------|----------|-------|---|
| Requirement TP166058 SSUK Added a reserb button to Service Menu > Maintenance Counts > Jam Count menu Problem TP16000 SSG Fixed an issue where the separator page was stapled together with the original printout Separator Page was applied to the PC driver. Problem TP16000 SSG Fixed an issue where the separator page was stapled together with the original printout Separator Page was applied to the PC driver. Problem TP16000 SSG Fixed prints are in front of "From" email address at the Scan to email function conspact PDF option Problem TP171017 SSA Fixed not to stuple every single page for multiple printing of one page. Requirement TP16608 SSBN Supported a special character Y in the LDAP search option. Added a function to automatically flust sermal address registered in the job account recipients when logging in and running Scan & Scan Options > Filename, real time will be used if it still has bates & Firm format, such as DDMMYY. VS.E6.04.01.0 4.4409 Problem TP171068 SSCA Fixed an issue where the Fix Reception Mode was set to DRPD and the ring pattern we memorized but it disappeared when the power was off and on. Problem TP171068 SSCA Fixed an issue where the Fix Reception Mode was set to DRPD and the ring pattern we memorized but it disappeared when the power was off and on. Problem TP172068 SSG Fixed an issue where the Fix Reception Mode was set to DRPD and the ring pattern we memorized but it disappeared when the power was off and on. Problem TP172068 SSG Fixed an issue that remaining error handling videos were not displayed when one of the simultaneous error handling videos was closed. Problem TP17306W SSG Fixed an issue date remaining error handling videos were not displayed when one of the simultaneous error handling videos was closed. Problem TP17306W SSG Fixed an issue of internal problem server in the sea as default at Scan & S address directory function. Problem TP17306W SSG Fixed an issue of internal problem server to this set as default at Scan & S address directory function. Problem TP17307C | R | Requirement | TP1670QW | SEA | • |
| Problem P16CDIQ SEG Separator Page was applied to the PC driver. Problem P16CDIQ SEA Seymator Page was applied to the PC driver. Problem P16CDIQ SEA Set Seymator Page was applied to the PC driver. Problem P16CDIQ SEA Set Seymator Page was applied to the PC driver. Problem P16CDIQ SEA Set Seymator Page was applied to the PC driver. Problem P1710DIT SEA Fire Intermittent issue that partially damaged PDF file is generated by color scanning compact PDF option. Requirement P1710DIT SEA Fired not to stuple every single page for multiple printing of one page. Requirement P1710DIT SEA Fired not to stuple every single page for multiple printing of one page. Requirement P1710DIT SEA Fired not to stuple every single page for multiple printing of one page. Requirement P1710DIT SEA Fired not to stuple every single page for multiple printing of one page. Requirement P1710DIT SEA Fired not to stuple every single page for multiple printing of one page. Requirement P1710DIT SEA SECH Sea Septiment P1710DIT SEA SEA | R | Requirement | TP16A0SB | SEUK | Added a reset button to Service Menu > Maintenance Counts > Jam Count menu |
| Problem TP16000 SEA As-1s: From: http://dx.numbers.com/problem-12/1007 SEA As-1s: From: http://dx.numbers.com/problem-12/1007 SEA Fixed not to staple every single page for multiple printing of one page. Problem TP171017 SEA Fixed not to staple every single page for multiple printing of one page. Problem TP160006 SECH Added a function to automatatically fill user email address registered in the job account of eccipients when logging in and running Scan & Send App. Problem TP171068 SECH Added a function to automatatically fill user email address registered in the job account of eccipients when logging in and running Scan & Send App. Problem TP171068 SECA Fixed an issue where the Fax Reception Mode was set to DRMMYY. As-is: rest_DDMMYY saved as 'test_DDMMYY'. To-Be: rest_DDMMYY saved | Р | Problem | TP16B0KD | SEG | Fixed an issue where the separator page was stapled together with the original printout when Separator Page was applied to the PC driver. |
| Problem TP171017 SEA Fixed not to staple every single page for multiple printing of one page. Requirement TP16909R SEBN Supported a special character '\text{in the LDAP search option.} Added a function to automatically fill user email address registered in the job account of ecipients when logging in and running Scan & Sead App. Problem TP16008 SECH Even an user changes filename format of Scan&Sead-Scan Options > Filename, real time will be used if it still has DateseXTime format, such as DDMMYY. a still a state of the state of | P | Problem | TP16C0JQ | SEA | As-Is: From: <sghj@ghj.com></sghj@ghj.com> |
| Requirement TP1600R SEBN Supported a special character \(\frac{1}{2} \) in the LDAP search option. | P | Problem | TP16C003 | SEG | Fix an intermittent issue that partialy damaged PDF file is generated by color scanning with compact PDF option. |
| Requirement TP1600R SEBN Supported a special character \(\frac{1}{2} \) in the LDAP search option. | P | Problem | TP171017 | SEA | Fixed not to staple every single page for multiple printing of one page. |
| Problem TP160EG SECH Added a function to automatically fill user email address registered in the job account of recipients when logging in and running Scan & Send App. | _ | | | | 1 1 1 1 1 1 1 1 1 |
| time will be used if it still has Dates&Time format, such as DDMMYY. ex) problem TP1710G8 SECA Problem TP1710G8 SECA Problem TP1710GB SECA Problem TP1710GB SECA Problem TP1710GB SECA Problem TP1710GB SECA Switch to fax sending job by deleting email address when entering fax numbers if email already put as a recipient at the Scan & Send app. Problem TP1720GB SEG Fixed an issue whare the Fax Reception Mode was set to DRPD and the ring pattern we memorized but it disappeared when the power was off and on. Switch to fax sending job by deleting email address when entering fax numbers if email already put as a recipient at the Scan & Send app. Problem TP1720GB SEG Fixed the black and white scan counts to be increased for scanning job with setting the mode to the mono. Problem TP1660L0 SEUK Added a function to select and take address directory from LDAP. Problem TP1730EW SEG Fixed not to print when user quota was exceeded while copying and printing simultane deletes the mono. Fixed an issue that when a PDF document created by a specific PDF generation tool we directory from UDAP result when Server tab is set as default at Scan & Staddress directory from USA, he output of the character spacing widened or an error occurred so output was not printed. Problem TP1730KE KOREA Problem TP1730KE SEA Fixed an issue that when a PDF document created by a specific PDF generation tool we directory from USA, he output of the character spacing widened or an error occurred so output was not printed. Fixed an issue of intering an e-mail as junk mail on Gmail server if the default messen and the problem in th | | · | | | Added a function to automatically fill user email address registered in the job account (JAC) in |
| Problem TP170G8 SECA memorized but it disappeared when the power was off and on. Problem TP1710MR SEA Switch to fax sending job by deleting email address when entering fax numbers if email aready put as a recipient at the Scan & Send app. Problem TP1720G8 SEG Fixed an issue that remaining error handling videos were not displayed when one of the simultaneous error handling videos was closed. Problem - DEV Fixed an issue that remaining error handling videos were not displayed when one of the simultaneous error handling videos was closed. Problem TP1660L0 SEUK Added a function to select and take address directory from LDAP. Problem TP1730EW SEG Fixed to select an item from LDAP result when Server tab is set as default at Scan & St address directory function. Problem TP1710GG SEBN United to select an item from LDAP result when Server tab is set as default at Scan & St address directory function. Fixed an issue that when a PDF document created by a specific PDF generation tool we directly from USB, the output of the character spacing widened or an error occurred so output was not printed. Problem TP1730KE KOREA Fix an error in PDF direct printing by abnormal font data included in the PDF file whice generated by specific PDF creator application. Problem TP160CMM SEAU Fixed an issue of filtering an e-mail as junk mail on Gmail server if the default message problem DEV Fixed an issue of displaying devices with the same MAC address at Fleet Admin Pros of TP172037 SEAA Fixed an issue of displaying devices with the same MAC address at Fleet Admin Pros of TP172037 SEAA Fixed an issue of intermittent disappearance of PC list by DB corruption when using SC Problem Problem Problem Problem SEA Fixed an issue of intermittent disappearance of PC list by DB corruption when using SC Problem Prob | 42409 | Problem | - | DEV | ex) As-Is: test_DDMMYY saved as "test_DDMMYY" |
| Problem Proble | P | Problem | TP1710G8 | SECA | Fixed an issue where the Fax Reception Mode was set to DRPD and the ring pattern was memorized but it disappeared when the power was off and on. |
| Problem | Р | Problem | TP1710MR | SEA | Switch to fax sending job by deleting email address when entering fax numbers if email was already put as a recipient at the Scan & Send app. |
| Problem - DEV mode to the mono. Problem - DEV Fixed not to print when user quota was exceeded while copying and printing simultane. Added a function to select and take address directory from LDAP. Problem TP1730EW SEG Fixed to select an item from LDAP result when Server tab is set as default at Scan & Staddress directory function. Problem TP1710GG SEBN Fixed an issue that when a PDF document created by a specific PDF generation tool we directly from USB, the output of the character spacing widened or an error occurred so output was not printed. Problem TP1730KE KOREA Fixed an issue of filtering an e-mail as junk mail on Gmail server if the default message Problem TP160KM SEAU Fixed an issue of filtering an e-mail as junk mail on Gmail server if the default message Problem TP1730F SEA Fixed an issue of displaying devices with the same MAC address at Fleet Admin Pro's of the device at SWS or FleetAdminPro. Created at FleetAdminPro where the device at SWS or FleetAdminPro. Created at FleetAdminPro where the device at SWS or FleetAdminPro. SEED Fixed an issue of intermittent disappearance of PC list by DB corruption when using SC Fixed an issue of admin password change as default when enabling SFE 019 function at SEA Fixed an issue of admin password change as default when enabling SFE 019 function at SEA Fixed an issue of admin password change as default when enabling SFE 019 function at SEA Fixed an issue of admin password change as default when enabling SFE 019 function at SEA Fixed an issue of admin password change as default when enabling SFE 019 function at SEA Fixed an issue of admin password change as default when enabling SFE 019 function at SEA Fixed an issue of admin password change as default when enabling SFE 019 function at SEA Fixed an issue of admin password change as default when enabling SFE 019 function at SEA Fixed parts are string to the device setting backup (cloning) when using address stored in Adress book to destination of program. | Р | Problem | TP1720G8 | SEG | Fixed an issue that remaining error handling videos were not displayed when one of the simultaneous error handling videos was closed. |
| Requirement TP1660L0 SEUK Added a function to select and take address directory from LDAP. Problem TP1730EW SEG Fixed to select an item from LDAP result when Server tab is set as default at Scan & Staddress directory function. Fixed an issue that when a PDF document created by a specific PDF generation tool we directly from USB, the output of the character spacing widened or an error occurred so output was not printed. Problem TP1730KE KOREA Fixed an issue that when a PDF document created by a specific PDF generation tool we directly from USB, the output of the character spacing widened or an error occurred so output was not printed. Problem TP160KM SEAU Fixed an issue of intering an e-mail as jukn mail on Gmail server if the default message problem - DEV Fixed an issue of filtering an e-mail as jukn mail on Gmail server if the default message problem - DEV Fixed an issue of filtering an e-mail as jukn mail on Gmail server if the default message fixed an issue of initializing Job accounting setup info. created at Fleet Admin Pro's on the device at SWS or Fleet Admin Pro. Problem - SEA Fixed an issue of intermittent disappearance of PC list by DB corruption when using SC Fixed an issue of unworked SFE behaviors when applying SFE27, SFE54 setup at issue problem - DEV Fixed an issue of admin password change as default when enabling SFE 019 function at Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Problem TP1670LW SEI Add "[.]," "to the folder name input function at Scan to SMB feature. Fix as issue that when a PDF document created by a specific PDF center appears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LW SEI Add "[.]," "to the fol | P | Problem | - | DEV | Fixed the black and white scan counts to be increased for scanning job with setting the color mode to the mono. |
| Problem TP1730EW SEG Fixed to select an item from LDAP result when Server tab is set as default at Scan & Scaddress directory function. Fixed an issue that when a PDF document created by a specific PDF generation tool we directly from USB, the output of the character spacing widened or an error occurred so output was not printed. Problem TP1730KE KOREA Fix an error in PDF direct printing by abnormal font data included in the PDF file whice generated by specific PDF creator application. Fixed an issue of filtering an e-mail as junk mail on Gmail server if the default message fixed an issue of displaying devices with the same MAC address at Fleet Admin Pro's control of the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Froblem Froblem Fixed an issue of intermittent disappearance of PC list by DB corruption when using SK fixed an issue of admin password change as default when enabling SFE 019 function at Fixed an issue of admin password change as default when enabling SFE 019 function at Fixed an issue of program. Froblem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement Problem TP1670UW SEI Add "[.], \"^* to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | P | Problem | - | DEV | Fixed not to print when user quota was exceeded while copying and printing simultaneously. |
| Problem TP1730EW SEB address directory function. Fixed an issue that when a PDF document created by a specific PDF generation tool was directly from USB, the output of the character spacing widened or an error occurred so output was not printed. Problem TP1730KE KOREA Fix an error in PDF direct printing by abnormal font data included in the PDF file whice generated by specific PDF creator application. Problem TP16COKM SEAU Fixed an issue of filtering an e-mail as junk mail on Gmail server if the default message Fixed an issue of displaying devices with the same MAC address at Fleet Admin Pro's or TP1710BP SEA Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro where the device at SWS or FleetAdminPro. Problem Froblem Fixed an issue of intermittent disappearance of PC list by DB corruption when using Sc Fixed an issue of unworked SFE behaviors when applying SFE27, SFE54 setup at issue of unworked SFE behaviors when applying SFE27, SFE54 setup at issue of more problem TP1670DJ SEA import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670LW SEI Add "[,], "* to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | R | Requirement | TP1660L0 | SEUK | Added a function to select and take address directory from LDAP. |
| Problem TP1710GG SEBN directly from USB, the output of the character spacing widened or an error occurred so output was not printed. Problem - DEV Improve double-sided printing speed of Executive paper size. Problem TP1730KE KOREA Fix an error in PDF direct printing by abnormal font data included in the PDF file whice generated by specific PDF creator application. Problem - DEV Fixed an issue of filtering an e-mail as junk mail on Gmail server if the default message Fixed an issue of displaying devices with the same MAC address at Fleet Admin Pro's or TP1710BP SEA Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of intentitent disappearance of PC list by DB corruption when using Sc Fixed an issue of intentitent disappearance of PC list by DB corruption when using Sc Fixed an issue of intentitent disappearance of PC list by DB corruption when using Sc Fixed an issue of intentitent disappearance of PC list by DB corruption when using Sc Fixed an issue of intentitent disappearance of PC list by DB corruption when using Sc Fixed an issue of intentitent disappearance of PC list by DB corruption when using Sc Fixed an issue of intentitent disappearance of PC list by DB corruption when using Sc Fixed an issue of admin password change as default when enabling SFE 019 function at Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep fixed an issue of the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | Р | Problem | TP1730EW | SEG | Fixed to select an item from LDAP result when Server tab is set as default at Scan & Send app's address directory function. |
| Problem TP1730KE KOREA Fix an error in PDF direct printing by abnormal font data included in the PDF file whice generated by specific PDF creator application. Problem TP16COKM SEAU Fixed an issue of filtering an e-mail as junk mail on Gmail server if the default message problem - DEV Fixed an issue of displaying devices with the same MAC address at Fleet Admin Problem TP16707Q SEDA Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro where the device at SWS or FleetAdminPro. Problem - SEF Fixed an issue of intermittent disappearance of PC list by DB corruption when using SC Fixed an issue of intermittent disappearance of PC list by DB corruption when using SC Fixed an issue of admin password change as default when enabling SFE 019 function at Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,],^" to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | P | Problem | TP1710GG | SEBN | Fixed an issue that when a PDF document created by a specific PDF generation tool was printed directly from USB, the output of the character spacing widened or an error occurred so that the output was not printed. |
| Problem TP16C0KM SEAU Fixed an issue of filtering an e-mail as junk mail on Gmail server if the default message Fixed an issue of displaying devices with the same MAC address at Fleet Admin Pro's of TP1710BP TP16707Q SEA Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Problem - KOREA Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of intermittent disappearance of PC list by DB corruption when using Sc Fixed an issue of unworked SFE behaviors when applying SFE27, SFE54 setup at issue of admin password change as default when enabling SFE 019 function at Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | P | Problem | - | DEV | Improve double-sided printing speed of Executive paper size. |
| Problem - DEV Fixed an issue of displaying devices with the same MAC address at Fleet Admin Pro's of TP1710BP TP16707Q TP172037 SEASA Problem - KOREA Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of intermittent disappearance of PC list by DB corruption when using Sc Fixed an issue of unworked SFE behaviors when applying SFE27, SFE54 setup at issue of admin password change as default when enabling SFE 019 function at Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | P | Problem | TP1730KE | KOREA | Fix an error in PDF direct printing by abnormal font data included in the PDF file which is generated by specific PDF creator application. |
| Problem - DEV Fixed an issue of displaying devices with the same MAC address at Fleet Admin Pro's of TP1710BP Problem - TP16707Q TP172037 SEASA Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro when the device at SWS or FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro. Fixed an issue of initializing Job accounting setup info. created at FleetAdminPro. Fixed an issue of intermittent disappearance of PC list by DB corruption when using Stevalue in the Copy / | P | Problem | TP16C0KM | SEAU | Fixed an issue of filtering an e-mail as junk mail on Gmail server if the default message was used |
| V5.E6.04 (2017-03-24) Problem TP16707Q TP172037 SEDA SEASA Problem - KOREA Fixed an issue of intermittent disappearance of PC list by DB corruption when using Sc Problem - SEF Fixed an issue of unworked SFE behaviors when applying SFE27, SFE54 setup at issue Problem - DEV Fixed an issue of admin password change as default when enabling SFE 019 function a Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | P | Problem | - | DEV | Fixed an issue of displaying devices with the same MAC address at Fleet Admin Pro's device list |
| (2017-03-24) Problem IP16/07Q SEDA the device at SWS or FleetAdminPro. Problem Problem Fixed an issue of intermittent disappearance of PC list by DB corruption when using Sc Problem SEF Fixed an issue of unworked SFE behaviors when applying SFE27, SFE54 setup at issue of a nissue of admin password change as default when enabling SFE 019 function at Problem TP1670DJ SEA | | | | | Fixed an issue of initializing Job accounting setup inforceated at Fleet AdminPro when rebooting |
| Problem TP1670DJ SEA Problem TP1670DU SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Problem TP1680AR SEA Fixed an issue of intermittent disappearance of PC list by DB corruption when using Sc Fixed an issue of unworked SFE behaviors when applying SFE27, SFE54 setup at issue of admin password change as default when enabling SFE 019 function at Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | | Problem | | | |
| Problem - SEF Fixed an issue of unworked SFE behaviors when applying SFE27, SFE54 setup at issue Problem - DEV Fixed an issue of admin password change as default when enabling SFE 019 function at Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | _ | Problem | TP172037 | | Fixed an issue of intermittent disappearance of DC list by DD compution when using Soon to DC |
| Problem - DEV Fixed an issue of admin password change as default when enabling SFE 019 function a Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | _ | | - | | |
| Problem TP1670DJ SEA Fix an issue that destination information disappears at program execution after address import and device setting backup (cloning) when using address stored in Adress book to destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | | | _ | | Fixed an issue of admin password change as default when enabling SFE 019 function at issued |
| Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | | | TP1670DJ | | Fix an issue that destination information disappears at program execution after address book import and device setting backup (cloning) when using address stored in Adress book to register |
| Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670UW SEI Add "[,], ^" to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | P | Problem | TP1670LQ | SEA | Allow mixed size to be default for original size value in the Copy / Send App, and keep the |
| Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | F | Requirement | _ | SEUK | |
| Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. | | | | | |
| Problem TP1690AR SEA - Correct a problem where the Duplex option didn't work at URF mode. | <u>P</u> | Problem | TP1680HV | SENA | † |
| - Fix an issue where portrait and landscape alternate when printing the same documen intermittently. | F | Problem | TP1690AR | SEA | - Correct a problem where the Duplex option didn't work at URF mode Fix an issue where portrait and landscape alternate when printing the same document |
| · | F | Problem | _ | DEV | Improve G3 fax transmission / reception quality and retry job protocol in VoIP environment. |
| Dividing TD1 (AOD) SEA Five problem where the machine reheats when using small paper that is not supported | - T | D l. 1 | TP16A0B5 | | Fix a problem where the machine reboots when using small paper that is not supported by DSDF. |
| V5.D6.15.04.0 Problem TP16B017 SEG Use a temporary file name while scaning and saving the file, and rename it after the sav | 5.D6.15.04.0 P | Problem | | | Use a temporary file name while scaning and saving the file, and rename it after the saving is |
| 11715 (2017 01 23) Problem TP16B0I7 SECA Fix an issue where JAC enable / disable do not work by job type via Fleet Admin Pro. | 11715 p | | TP16B0I7 | SECA | Fix an issue where JAC enable / disable do not work by job type via Fleet Admin Pro. |

| oblem 'oblem 'oblem ' | TP16B0LX TP16B0ON TP16B0SM | SEPOL SEI | Fix a problem that causes the device to freeze when the scanned image is skewed from the Searchable PDF option setting at scanning. Fix a problem that cause performance degradation when using counter widget. |
|-----------------------|--|--|--|
| oblem ' | | | Fix a problem that cause performance degradation when using counter widget. |
| oblem ' | TP16B0SM | | |
| | | SEF | Fix an issue where the total sent page is incorrectly displayed in the fax sent report when retransmitting due to an error occurred during fax transmission. |
| oblem | TP1690PR | SEG | Fix machine stop when setting the Compact PDF option and changing color setting to Mono in Easy setting during scan. |
| | TP16A0OQ | SEA | Correct the problem that certain SFE functions are turned off after HDD recovery. |
| equirement - | - | DEV | Add HDD defect check function in HDD recovery mode screen. |
| equirement - | - | KOREA | Improve fax widget button size and space between buttons for user convenience. |
| oblem ' | TP1670VH | SEG | Fix the problem where scan data transfer is slowed down for a sync problem when there are a lot of files in the target folder at the Scan to SMB function. |
| oblem | - | DEV | Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle |
| oblem ' | TP1670DJ | SEA | Fix an issue that destination information disappears at program execution after address book import and device setting backup (cloning) when using address stored in Adress book to register destination of program. |
| oblem | TP1670LQ | SEA | Allow mixed size to be default for original size value in the Copy / Send App, and keep the mixed size setting value when creating a program. |
| equirement - | - | SEUK | Fax paper source tray setting is added to SWS. |
| oblem | TP1670UW | SEI | Add "[,], ^" to the folder name input function at Scan to SMB feature. |
| oblem | TP1680HV | SENA | Add Umlaut charset to the folder name input function at Scan to SMB feature. |
| oblem | TP1690AR | SEA | Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. - Fix an issue where portrait and landscape alternate when printing the same document intermittently. |
| oblem - | - | DEV | Improve G3 fax transmission / reception quality and retry job protocol in VoIP environment. |
| oblem | TP16A0B5 | SEA | Fix a problem where the machine reboots when using small paper that is not supported by DSDF. |
| oblem | TP16B017 | SEG | Use a temporary file name while scaning and saving the file, and rename it after the saving is completed to improve errors caused by access to a file that has not been completely saved. |
| oblem | TP16B0I7 | SECA | Fix an issue where JAC enable / disable do not work by job type via Fleet Admin Pro. |
| oblem | TP16B0LX | SEPOL | Fix a problem that causes the device to freeze when the scanned image is skewed from the Searchable PDF option setting at scanning. |
| oblem | TP16B0ON | SEI | Fix a problem that cause performance degradation when using counter widget. |
| oblem | TP16B0SM | SEF | Fix an issue where the total sent page is incorrectly displayed in the fax sent report when retransmitting due to an error occurred during fax transmission. |
| oblem | TP1690PR | SEG | Fix machine stop when setting the Compact PDF option and changing color setting to Mono in Easy setting during scan. |
| oblem ' | TP16A0OQ | SEA | Correct the problem that certain SFE functions are turned off after HDD recovery. |
| equirement | - | DEV | Add HDD defect check function in HDD recovery mode screen. |
| equirement - | - | KOREA | Improve fax widget button size and space between buttons for user convenience. |
| oblem ' | TP1670VH | SEG | Fix the problem where scan data transfer is slowed down for a sync problem when there are a lot of files in the target folder at the Scan to SMB function. |
| oblem | - | DEV | Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle problems to false IP alarms (false alarms). |
| oblem | TP16B0QL | SEG | Fix the problem that the device may reboot intermittently when switching from duplex to simplex printing during a large number of continuous printing job. |
| oblem | - | DEV | Fix the device stop when setting double-sided, 400% enlarge option in copy job . |
| oblem ' | TP1690W6 | SEF | Fixed several bouygues telecom issues. - Fixed the App and Widget are disappeared in home screen in Ubiquitech. - Fixed the layout and button are broken in Ubiquitech. - Fixed the job pending issue when the home button was selected before Send Job is completed with Skip blank page enabled. |
| oblem | TP16B0CT | SEAU | Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized with Searchable PDF enabled |
| oblem | | KOREA | Fixed the error page not being printed abnormally in the solution environment's printing case. |
| oblem | TP16B057 | SEF | Fixed the Mono printer issue of job being canceled when the job was sent to color print driver with Application authentication on |
| oblem ' | TP16B027 | KOREA | Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the time of quota reset. |
| | oblem quirement oblem | oblem TP1670LQ quirement - oblem TP1680HV oblem TP1680HV oblem TP1680HV oblem TP1680B5 oblem TP16B017 oblem TP16B017 oblem TP16B0LX oblem TP16B0N oblem TP16B0N oblem TP16B0N oblem TP16B0N oblem TP16A0OQ quirement - oblem TP1670VH oblem TP16B0QL oblem TP16B0QL | belem TP1670LQ SEA quirement - SEUK belem TP1670LW SEI belem TP1680HV SENA belem TP1680HV SEA belem TP1680HV SEA belem TP1680HV SEA belem TP1680I7 SEG belem TP16B0I7 SECA belem TP16B0LX SEPOL belem TP16B0N SEI belem TP16B0N SEI belem TP16B0N SEG belem TP16A0QQ SEA quirement - DEV quirement - DEV belem TP16A0QQ SEA collem TP16A0Q |

| | | TP1630R0 | | |
|------------------------|----------------------------|--|--------------------|--|
| | Requirement | VO-1506- 000610 VO-1507- | SEA SECA SEG | Developed a new app for full build job support (The app will be released in the app center next Regualr FW release officially). |
| | | 000139 | SEG | |
| | Requirement | - | DEV | Developed a new Smart Scan app (The app will be released in the app center next Regualr FW release officially). |
| | Problem | - | DEV | Fixed the Schedule Image Overwrite automatically changing from on to off when powering the device on or off. |
| | Problem | - | DEV | Improved screen transition speed between tabs on UI OOB app. |
| V5.D6.15.03.1 | Requirement | TP164027 | SEA | Modified the LDAP contact usernames to display either surname or given name. |
| 020609 | Requirement | TP1640FF | SEA | Added a default contact selection feature between LDAP and local contacts in the Send app. |
| (2016-12-08) | Requirement | TP1650OK | SEA | Added SSO support to allow LDAP search using Kerberos ID/PW. |
| | Requirement | TP165011 | SEG | Added the Borderless printing feature. (SFE56) |
| | Requirement | TP1660JA | SEA | Added buckle adjustment feature in the service mode. |
| | Problem | TP16611L | SEUK | Fixed the intermittently changing home screen setting issue with wifi enabled. |
| | Problem | TP1670O8 | SEA | Fixed the VNC connection issue when using a password with a certain character. |
| | Problem | TP168030 | SEA | Fixed the intermittent booting issue after a FW update fail. |
| | Problem | TP1680K1 | SEIL | Fixed the issue of VNC setting menu not showing correctly in Hebrew. |
| | Problem | TP1670IC | KOREA | Fixed remaining roller counts showing as negative numbers in the Counthru environment. |
| | Problem | - | KOREA | Fixed imaging unit or toner cartridge being recognized as uninstalled at times. |
| | Problem | TP169064 | SENA | Fixed the printing error when using remote pull printing in the Printing Security Core solution. |
| | Problem | TP1680JH TP1670W4 | SEAU | Fixed fax reception stopping with an invalid caller ID coming through. |
| | Requirement | TP1690AQ | SECA | Added Letter/Legal MSO fax reception functionality. |
| | Problem | TP1690MM | SENA | When selecting fixed the menu display revert Swedish or Hungarian language, the device storage menu screen is reverted. |
| | Problem | TP1640A0 | SEAU | When entering D or d after connecting external keyboard to USB, input value is not displayed properly and going back to the previous screen. |
| | Problem | TP1680UX | SEG | In PCL5 printing, outbin setting of Mailbox is not working. Instead, all are printed as basic output bin. |
| | Problem | TP16A020 | SEUK | When pushing start button before From/To values of send app are prefilled, send job is not working from time to time. |
| | Problem | TP16A0FH | KOREA | SFE feature setting value changes to default from time to time. |
| | Requirement | SR-1508- 000118 VO-1508- 000350 | SEA | The total user accounts increased from 500 to 2000. |
| | Fixed issue | TS-1512- 000029 | SEAU | Intermittent job pending issue during scanning a large volume of media with compact PDF as an option was resolved . |
| | Requirement | TP1640K502 | SEG | Printing on a number of paper types including Letterhead / Punched / Preprinted was improved -Fixed wrong application of staple when staple option is selected. |
| | Fixed issue | TP1660HG01 | SEG | Modified mistranslation in German |
| | Fixed issue | TP1660GU01 | SEA | Intermittent print job stoppage when user processes complete after DSDF jam. |
| | Requirement | TP1650IT01 | KOREA KOREA | Added a feature that can allow FAP monitoring of inactivation function of USB memory stick. Added an option that enables changing the priority order of multi-use paper tray during copy, |
| | Requirement Fixed issue | TP1650PP01 TP1660VG01 | SEA | S5-3111 error not being displayed in error report was fixed. |
| V5.D6.15.02.1 02513 | | TP16616201 | SEDA | Fixed the issue of which the printer continues to print from a printable tray rather coming to a halt at the tray empty point selected by user when a different tray option is applied per page within a single job. |
| (2016-10-31) | Fixed issue | TP16703Z01 | SEA | Took out the description about features that are not applied to Help app. |
| | Fixed issue | TP16705401 | KOREA | Resolved the issue of system user being logged on instead of an actual print user when the user logs out while printing with print security solution. |
| | Fixed issue | TP16701V01 | SEA | Fixed the issue of +Me Box still running even when Box Application is disabled. |
| | Requirement | TP1630TE03 | SEF | Added an option to maintain Jam animation until error is cleared. |
| | Fixed issue | TP16709701 | SEBN | Secured a compatibility of PDF/A Scan file with ISO 19005-1. |
| | Requirement | TP1670DA01 | KOREA | Added a feature to allow use or delete scan/ transmission destination. |
| | Fixed issue | TP1660NE01 | SESA | Resolved the issue of which reduced information, which was saved when program is generated, |
| | Requirement | TP1670PP01 | KOREA | Added a function that aggregates usage data within a certain period of time selected by Counter App user. |
| | Fixed issue | TP16601Y | SEUK | Fixed user being automatically logged out while using MagStipe Readers login. |
| | Fixed issue | TP16502A | KOREA | Improved the issue of the system slowing down in DHCP mode without DHCP server |
| | Fixed issue | TP1680J3 | SECA | Fixed MP tray setting value is changed after Power on/off in case of envelop size. |
| <u> </u> | Fixed issue | TP16706H | SECH | Fixed slow printing issue when the set enables JAC Fleet Admin. |

| V5.D6.15 (2016-09-05) * Not included V5.D6.14.01.0 81720 items. | Fixed issue | | SEM KOREA | Fixed toner supply error in case of a big temperature changing environment. |
|--|-------------|--|-----------------------|--|
| | Requirement | VO-1509- 000191 SR-1507- 000561 | SEG SEF | Adding a feature to align the secure job list in LIFO and FIFO forms as preferred by user. |
| | Requirement | TP1650L8 | SEDA- SIMPRES S | Adding a feature to turn on/off alarm for toner status when it's low. |
| | Requirement | SR-1507- 000568 | SEG | Adding a selecting feature for a paper tray and a media type using a PJL command. |
| | Requirement | SR-1507- 000568 | SEG | Adding a feature of sending state information only when the entire job is completed for any job linked to VPSX server. |
| | Requirement | SR-1506- 000840 VO-1410- 000185 | SEBJ SEA Korea | Adding a PC scanning feature using a USB cable. |
| | Requirement | TS-1508- 000397 | SEDA | Supporting UBS flash drive in NTFS format. |
| | Requirement | SR-1509- 000477 | Korea | Adding a feature for making a document box invisible to users who login as SWS when admin disables the box. |
| | Requirement | VO-1511- 000153 SR-1601- 000115 VO-1511- 000059 TP1660B4 TP16610P | SECA Korea SEI | Adding a feature to allow users reboot a set at their desired time/cycle. |
| | Fixed issue | TS-1511- 000581 TS-1511- 000582 TS-1511- 000583 | SEF | Improving the issue with intermittent failures when setting options for copy and/or authorization as Fleet Admin. |
| | Requirement | VO-1508- 000490 | Korea | Disabling warning messages when the cover is open during platen scan. |
| | Requirement | VO-1509- 000398 | SEUK | Adding a delete and a preview feature during box printing. |
| | Requirement | SR-1510- 000416 | SELV | Modified to print a box-saved PRN file with Drive options that were applied when generating the PRN. |
| | Requirement | VO-1511- 000388 | SEF | Adding a feature to display telephone numbers or names (as saved in the address book) in the Fax Sent Report. |
| | Requirement | VO-1411- 000459 VO-1511- 000431 | SENA SEF | Adding a Test button in the E-mail notification setting for an SMTP check. |
| V5.D6.14.01.0 | Requirement | SR-1512- 000207 | SAPL | Adding a feature to reset a user's personal accounting information. |
| 81720 (2016-08-19) | Fixed issue | TP1640HA | SEAU SEF | Corrected the problem of a job being cancelled when Print job control is OFF and FDI balance is 0. |
| | Fixed issue | SR-1512- 000319 | SENA | Improving authentication errors when an FTP password contains ":". |
| | Fixed issue | TS-1601- 000638 | SEBN | Correcting the problem of test pattern not being printed in a service mode. |
| | Fixed issue | TP16500K | SEF | Improving the recognition failure of Skip blank feature during a low resolution scan (100dpi). |
| | Fixed issue | Q1603_0175 | Korea | Improving the connection failure problem due to non-support for NOOP command in a certain SMTP server. |
| | Fixed issue | TP1630CO | SEBN | Adding additional paper types in the selection during Google cloud printing. |
| | Fixed issue | TP1630PW | Korea | Correcting intermittent failures of Color mode printing or color document being printed in mono during auto copying. |
| | Fixed issue | Q1603_0263 | Korea | Correcting intermittent Power off malfunctions in NFC user interface. |

| Fixed issue TP1640EO SEBN Improving intermittent Kerberos authentication errors due to timing iss Fixed issue TP1640EO SEBN Improving poor Dutch translation. Fixed issue TP1640F8 SEAU Improving the issue of Multi destination emails not being sent when usi Requirement SR-1503- 000854 SEA Adding a feature to recognize papers smaller than A4.Letter as A4.Letter Requirement SR-1509- 000006 Korea Adding a feature to include PSTN line state information in Fax Diagnor Requirement TP1650U601 Korea Supporting special characters (<, >, ") for a password. (If usage environced to B2B driver and solution) | |
|--|-----------------------------|
| Fixed issue TP1640F8 SEAU Improving the issue of Multi destination emails not being sent when using Requirement SR-1503-000854 SEA Adding a feature to recognize papers smaller than A4.Letter as A4.Letter Requirement SR-1509-00006 Korea Adding a feature to include PSTN line state information in Fax Diagnost Supporting Special characters (<, >, ") for a password. (If usage envirage and the state of the state information in Fax Diagnost Supporting Special characters (<, >, ") for a password. (If usage envirage and the state of th | |
| Requirement 000854 SEA Adding a feature to recognize papers smaller than A4.Letter as A4.Letter | er during scanning. |
| Requirement 000006 Korea Adding a feature to include PSTN line state information in Pax Diagnos Supporting special characters (<, >, ") for a password. (If usage envir | |
| | stic Report. |
| | roments is solution, then |
| Fixed issue TP1630CY Korea Improving reading errors when using EPSoft card readers. | |
| Fixed issue TP16500S SEA Improving print errors due to wrongly generated data during LPD/LPR | print data processing. |
| Fixed issue TP1640IT SSA Improving the issue of completed secure print job remaining on the job | list. |
| Fixed issue TP1630AU SEA When previewing PDF or TIFF images on Box App, the previewed images on Box App, the Bo | ge may have unexpected |
| Fixed issue TP1630FS SEA TP1661SE SECA During Scaning with compact PDF option, Set locks up at times. | |
| Fixed issue TP16403C SEAU Fixing memory leackage issue according to repeated solution install/un | install. |
| Fixed issue TP1640IZ SEG The poor German translation(StauWdrherste) will be changed. | |
| Requirement SR-1508- 000346 SESA Adding specific setting method through PJL command. - PCL font size, Tray1 paper size, Mp Tray paper size | |
| Fixed issue TS-1603- 000018 SEUK Correcting the problem of complex PDF document not being printed in | termittently. |
| Requirement SR-1507- 000265 SEG SEAU Adding Numeric keypad for PIN code input in solution (API only). | |
| Requirement SEUK Adding APK installation method in the Fleet Admin Pro. | |
| Fixed issue TP16613F SEA Fixing wrong IP address displaying on the notification screen in case of | DHCP mode. |
| Fixed issue TP16502T SEA Fixing powerpoint abnormal output from MAC office 2016. | |
| Fixed issue TP1640KG SEG Improving performance of 1-bit indexed color image document. | |
| Fixed issue TP16706H SECH Fixing printing job pending issue according to authentication fail. | |
| Fixed issue TP1650AD Korea Improving scanning speed when user sends many fax images. | |
| Fixed issue TP1640DH SEUK Enhanced overall UI performance for a case where a device supports m IDs. | ore than 501 external user |
| Fixed issue TP16500R SEG Fix inability to use '\$' character in Scan to SMB path. | |
| Fixed issue TP165051 SME Fix occasional inoperability on Copy Widget + buttons. | |
| Fixed issue TP1660OX KOREA Fix printing jobs are held at times when burst job request is received. | |
| Fixed issue TS-1601- 000563 SESG Fixed a job pending issue during Scan to SMB using NetApp SMB serv | er. |
| Fixed issue TP16303L03 SESG Fixed an issue of user email not being prefilled in Send App during the Auth Mode while using Safecom solution. | Basic and Application |
| Fixed issue TP16303L03 SESG Fixed an issue of Safecom pull print application closing immediately at the safecom login operations for time-dependent cases. | fter a user login. Enhanced |
| Fixed issue TS-1601- 000202 SENA Enhanced user login performace (reduced the login time) for a case wh print jobs are stored in a device. | ere hundreds of secure |
| Fixed issue TP1630D701 SEI Applied a scan authority checking process for a case where Dynamic With the Application Auth mode before Send Applaunches after the device I | |
| Fixed issue TP1640XN SEI Enhanced copy widget performance for a case where a user tries to con after a device boots up or wakes up from a power save mode. | duct a job immediately |
| V5.D6.14 Fixed issue TP1630TE SEF Disabled the PDF/A option for 600 dpi resolution in Send app. | |
| (5-July-2016) Fixed issue TP1630HK SEBN Fixed an issue of not cloning the authentication status in the admin sett | ing for printing. |
| Fixed issue TS-1601- 000468 SEAU Fixed an issue of scan images having a light background when a scan jo Color : Color/Mono" option on. | bb is done with an "Auto |
| Fixed issue TP1630CM SEA Fixed an issue of device card login not working sometimes in a sleep m | iode. |
| Fixed issue TS-1602- 000038 SEA Enhanced print performance for duplex images (color/mono mixed images) | iges). |
| Fixed issue TS-1603- 000002 SEA Added more animations for paper jam clearing guidance. | |
| | |
| Fixed issue TS-1511- 000148 SEA Made Scan to FTP compatible with Serv-U FTP server. | |
| I Eixed issue I ISEA IMade Scan to FTP compatible with Serv-U FTP server | Quick Copy in a Device |

| | Fixed issue Fixed issue Fixed issue | TP1630RG TP1640H0 TP165022 | KOR KOR | Enhanced Copy widget printout performance to be as powerful as that of Copy App. Enhanced secure job cancel function to delete received data completely. |
|-------------------|---|----------------------------------|--------------|--|
| <u> </u> | Fixed issue | | IZOD | |
| ţ | | | KOR | Fixed Autologout not working sometimes in the Device UI. |
| L- | Requirement | - | | Applied security compliance requirements from the Korean Government. |
| | Fixed issue | - | | Fixed a 4K-Finisher jam error which occured when an OHP flim is used for copy. |
| | Fixed issue | _ | | Improved the management of the IP filtering feature and its default values. |
| | Fixed issue | N/A | KOREA | Print jobs are held at times when SecuThru (a secure printing software) is used. |
| | | TS-1602- | | |
| - - | Fixed issue | 000104 | SEAU | GCP service fails as an expired key is not refreshed. |
| | Fixed issue | N/A | SEAU | The fax redials the number that was previously entered when dialing using the fax keypad under certain conditions. [Conditions for Reproduction] * Condition 1: Turn Job Progress Window off and Fax Confirmation Report on. Keep the previously dialed fax destination number. * Condition 2: Delete the fax number from step 1 and enter a new fax number using the keypad and hit start. |
| | Fixed issue | N/A | SEAU | Send Job Cancel does not work at times right after starting Send Job when the Searcheable PDF option is on. The UI also locks up on and off under certain conditions. [Conditions for Reproduction] * Condition 1: Turn Job Progress Window off and turn Searcheable PDF & Skip Blank Page on. * Condition 2: Cancel the job within 7 seconds after the job starts. |
| V5.D6.11 | Requirement | N/A | SEA | New US standard setting values were applied. (Default values for US models) - Auto continue: ON - MP Tray confirm: OFF - Paper Substitution: ON - Tray Priority: Tray1->Tray2->>MPTray - Toner/Imaging unit Alert Value: 5 - Black Optimization: On |
| (25-Mar- 2016) | Fixed issue | TS-1602- 000076 | SEG | When making a searcheable PDF with a 300 dpi or lower resolution, scanned images are cropped and the text on the scans is hard to read in MS Word. |
| | Fixed issue | TS-1601- 000454 | SEAU | The device locks up intermittently during scan when Job Progress Window is off. |
| | Fixed issue | TS-1601- 000564 | SEUK/SE G | Send does not work at times when Skip Blank Page is on. |
| | Fixed issue | SR-1602- 000397 | SEA | Scan to SMB fails if filename contains a space. |
| | Fixed issue | TS-1512- 000456 | SEBN | The number of copies cannot be selected when IPP printing in MAC OS. |
| | Fixed issue | N/A | KOREA | Scan to PC shortcuts generated in a previous version $(Vx.C6.xx)$ do not work after upgrading to $Vx.D6.04$. |
| | Fixed issue | SR-1601- 000384 | SEI/SEG | Fax confirmation reports are not printed to fit one page. |
| | Fixed issue | TP16307B | SEA | If the top bin of an inner finnisher is selected as the output tray, UI progress information is updated slowly. Also, the device slows down when handling 15 copies or more. |
| | Fixed issue | SR-1601- 000624 | SEA | If Home Lock is enabled for all users, duplicate icons appear on the Home screen at times. |
| | Fixed issue | SR-1601- 000624 | SEA | If a user changes the setting of Copy Customizer, the copy OOB setting also changes. |
| | Fixed issue | TS-1602- 000036 | SEA | The Compact PDF option does not work when scanning with the Auto Color Mode on. |
| | Fixed issue | TS-1602- 000036 | SEA | Scan Adjustment was modified to work according to the default paper size (A4 or Letter) of a country/region in which the machine will be used. |
| | Fixed issue | TS-1601- 000186 | SEA | An output tray selected for incoming faxes changes back to the default tray after waking up in a power save mode. |
| | | Add Func | | Support function to create "Web page" shortcuts on the main UI. |
| | | Add Func | | Support Scan ACS Function : In send app, "Auto" Mode (Automatic Color selection) is added. |
| | | Add Func | | Added PIN only authentication mode. |
| | | | | Skip Blank Page feature for Scan/Copy implemented. |
| | | Add runc | | |
| | | Add Func Add Func | | Error code and description improved. Provides detailed information. |

| Add Func If 'Staple Empty' error added. The User can select Continue or Hold. Add Func Add Officio size for Copy, Scan. Add Func Scan to SMB with browsing. New application to help customers to download and upgrade ROM manu Smart update application. Add Func Support Searchable PDF + PDF/A option. Add Func Reduced the file size of searchable PDF (OCR PDF). Add Func SSL, TLS, None are supported for SMTP from SWS. Fix defect The paper option is displayed Custom size on Apple device. Fix defect When two interface (Ethernet/Wifi) have same IP Address. IP conflict en Fix defect ID/PW values for Job Accounting are missing when user sets 'Preset' feat Fix defect The machine stops intermittently when the Customer is using the copy W | nally/automatically using |
|---|---------------------------|
| Add Func Scan to SMB with browsing. New application to help customers to download and upgrade ROM manu Smart update application. Add Func Support Searchable PDF + PDF/A option. Add Func Add Func Reduced the file size of searchable PDF (OCR PDF). Add Func SSL, TLS, None are supported for SMTP from SWS. Fix defect The paper option is displayed Custom size on Apple device. Fix defect When two interface (Ethernet/Wifi) have same IP Address. IP conflict en Fix defect ID/PW values for Job Accounting are missing when user sets 'Preset' featt Fix defect The machine stops intermittently when the Customer is using the copy W | nally/automatically using |
| Add Func New application to help customers to download and upgrade ROM manu Smart update application. Add Func Support Searchable PDF + PDF/A option. Add Func Reduced the file size of searchable PDF (OCR PDF). Add Func SSL, TLS, None are supported for SMTP from SWS. Fix defect The paper option is displayed Custom size on Apple device. Fix defect When two interface (Ethernet/Wifi) have same IP Address. IP conflict en Fix defect ID/PW values for Job Accounting are missing when user sets 'Preset' featt Fix defect The machine stops intermittently when the Customer is using the copy W | nally/automatically using |
| Add Func Support Searchable PDF + PDF/A option. Add Func Reduced the file size of searchable PDF (OCR PDF). Add Func SSL, TLS, None are supported for SMTP from SWS. Fix defect The paper option is displayed Custom size on Apple device. Fix defect When two interface (Ethernet/Wifi) have same IP Address. IP conflict en Fix defect The machine stops intermittently when the Customer is using the copy W | |
| V5.D6.04 (08-Jan-2016) Add Func Reduced the file size of searchable PDF (OCR PDF). Add Func SSL, TLS, None are supported for SMTP from SWS. Fix defect The paper option is displayed Custom size on Apple device. Fix defect When two interface (Ethernet/Wifi) have same IP Address. IP conflict en Fix defect ID/PW values for Job Accounting are missing when user sets 'Preset' feat Fix defect The machine stops intermittently when the Customer is using the copy W | |
| (08-Jan-2016) Add Func SSL, TLS, None are supported for SMTP from SWS. Fix defect The paper option is displayed Custom size on Apple device. Fix defect When two interface (Ethernet/Wifi) have same IP Address. IP conflict en Fix defect ID/PW values for Job Accounting are missing when user sets 'Preset' feat Fix defect The machine stops intermittently when the Customer is using the copy W | |
| Fix defect The paper option is displayed Custom size on Apple device. Fix defect When two interface (Ethernet/Wifi) have same IP Address. IP conflict en Fix defect ID/PW values for Job Accounting are missing when user sets 'Preset' feat: Fix defect The machine stops intermittently when the Customer is using the copy W | |
| Fix defect When two interface (Ethernet/Wifi) have same IP Address. IP conflict en Fix defect ID/PW values for Job Accounting are missing when user sets 'Preset' feat Fix defect The machine stops intermittently when the Customer is using the copy W | |
| Fix defect ID/PW values for Job Accounting are missing when user sets 'Preset' feat: Fix defect The machine stops intermittently when the Customer is using the copy W | |
| Fix defect The machine stops intermittently when the Customer is using the copy W | |
| | |
| Fix defect If Application Authentication is enabled, previouly created short-cut does | |
| | s not work. |
| | |
| | _ |
| | |
| | · |
| | |
| | |
| • | _ |
| Fix defect Booklet printing speed is improved. | |
| Fix defect User is not able to edit Wi-Fi IP settings. IP Setting menu from UI is disal | bled intermittently. |
| Add func. Support Korean language file name on ScanToPC menu. | |
| Add func. Supply security patch for Apk integrity. Machine who study your wards at transitions in case Machine is tyred. | l on by ooft norman on |
| Fix defect Machine rebooted very very rarely at receiving in case Machine is turned | on by soft power on. |
| Fix defect Fix defect that user can't cancel current job sometimes. | |
| Fix defect Fix defect of showing S5-3111 error on UI after sending print job while n mode. | nachine stays in sleep |
| Fix defect Fix defect that machine will not wake up from UI sleep mode in spite of | wake up event. |
| Fix defect | book CSV file under |
| Fix defect Fix wrong translation in Finnish. | |
| Fix defect Fix Scan & send App to launch properly. | |
| Fix defect Fix defect of not deleting job list in UI. | |
| Fix defect Fix defect that XOA-Web login page issue. (showing home page instead of the control | of Xoa application page) |
| V5.C6.11 (8-Sep-2015) Add func. Supporting the filename in send UI allowing to enter currencies. | |
| Fix defect Fix defect of not working copy widget. | |
| Add func. Add function to Send App of removing destinations after the Job is starte | d. |
| Fix defect that the Send App was crashed while launching the program w sometimes | ith Auto start option, |
| Fix defect Fix defect of rebooting by internal buffer overrunning. | |
| Fix defect Fix defect of rebooting and broken image on 2-2 copy. | |
| Fix defect Fix defect of broken image on duplex print (A5 SEF 2 - 2 book copy To N | MP Tray with Finisher). |
| Fix defect Fix defect that when user adds manual route entry in routing table through user defined entry is lost and user is not able to set Wifi as default gateway. | • |
| Add func. Add function of increased Font Size to 26 DP in Send application. | |
| ** | |
| Fix defect Fix file name issue of Korean character in ScanToPC. | |
| Fix defect Fix file name issue of Korean character in ScanToPC. Fix defect Fix defect that traditional Chinese is not applied in Settings. | |
| Thi detect | |
| Fix defect Fix defect that traditional Chinese is not applied in Settings. | |
| Fix defect Fix defect that traditional Chinese is not applied in Settings. Fix defect Fix defect of stop 2-2 copy job. V5.C6.08 Fix Defect Change Fuser release control behavior. | |
| Fix defect Fix defect that traditional Chinese is not applied in Settings. Fix defect Fix defect of stop 2-2 copy job. V5.C6.08 (29-Jul-2015) Fix Defect Change Fuser release control behavior. | progress. |
| Fix defect Fix defect that traditional Chinese is not applied in Settings. Fix defect Fix defect of stop 2-2 copy job. V5.C6.08 (29-Jul-2015) Fix Defect Change Fuser release control behavior. Fix Defect Fix not for launching Send App. | progress. |
| Fix defect Fix defect that traditional Chinese is not applied in Settings. Fix defect Fix defect of stop 2-2 copy job. V5.C6.08 (29-Jul-2015) Fix Defect Change Fuser release control behavior. Fix Defect Fix not for launching Send App. Fix Defect App crash is observed if user taps on to the UI while image loading is on | progress. |
| Fix defect Fix defect that traditional Chinese is not applied in Settings. Fix defect Fix defect of stop 2-2 copy job. V5.C6.08 (29-Jul-2015) Fix Defect Change Fuser release control behavior. Fix Defect Fix not for launching Send App. Fix Defect App crash is observed if user taps on to the UI while image loading is on Fix Defect PaperCut flicking issue. | progress. |
| Fix defect Fix defect that traditional Chinese is not applied in Settings. Fix defect Fix defect of stop 2-2 copy job. V5.C6.08 (29-Jul-2015) Fix Defect Change Fuser release control behavior. Fix Defect Fix not for launching Send App. Fix Defect App crash is observed if user taps on to the UI while image loading is on Fix Defect PaperCut flicking issue. Fix Defect SWS set 400%, Copy show 400 %. but output paper is 100%. | progress. |
| Fix defect Fix defect Fix defect that traditional Chinese is not applied in Settings. Fix defect Fix defect of stop 2-2 copy job. V5.C6.08 (29-Jul-2015) Fix Defect Change Fuser release control behavior. Fix Defect Fix not for launching Send App. Fix Defect App crash is observed if user taps on to the UI while image loading is on Fix Defect PaperCut flicking issue. Fix Defect SWS set 400%, Copy show 400 %. but output paper is 100%. Fix Defect Scan to USB job is not happening after OHD Job. | progress. |
| Fix defect Fix defect Fix defect that traditional Chinese is not applied in Settings. Fix defect Fix defect of stop 2-2 copy job. V5.C6.08 (29-Jul-2015) Fix Defect Change Fuser release control behavior. Fix Defect Fix not for launching Send App. Fix Defect App crash is observed if user taps on to the UI while image loading is on Fix Defect PaperCut flicking issue. Fix Defect SWS set 400%, Copy show 400%. but output paper is 100%. Fix Defect Scan to USB job is not happening after OHD Job. Fix Defect Copy Save to box -> Store and print file name overwrite issue. | |

| (30 -3 uii-2013) | | |
|-------------------------------|------------|---|
| | | Fix Fax Widget issue |
| | Fix Defect | 1. Fax Widget hangs due to hard copy security NULL value. |
| | | Sometimes fax number goes as empty and Job will not happen. Sometimes start button is disabled and not enabled. |
| | F. D.C. | |
| | Fix Defect | Fixed memory issues, it was crashing applications due to low memory. |
| | Fix Defect | Watermark Icon change. |
| | Fix Defect | After reboot, all Send programs was not displayed on HOME. |
| VE CC OF | Fix Defect | MFP was not discovered as Airprint device from MAC OS. |
| V5.C6.05 (18-May- 2015) | Fix Defect | Staple malfunction when coping 2 originals |
| 2013) | Add Func. | Add new Hebrew strings. |
| | Fix Defect | AMPV value is not correct with actual amount of usage. |
| | Fix Defect | Box app close automatically if set Job Progress Window as Off and select a file and do print in Box app. |
| | Fix Defect | |
| TIE C(04 | Fix Defect | Scan to Email functionality improved. Custom Paper size in Settings are not showed in Tray Confirmation pop-up window. |
| V5.C6.04 (15-May- | TIX Delect | |
| 2015) | Fix Defect | In Send App, after making the Job Progress Window OFF from Settings. Only first was able to be performed. Next jobs was not allowed to proceed due to a invalid check in UI. |
| | Fix Defect | Fix f/w issue that can occur using easy launcher with xoa-e login solution. |
| | Fix Defect | Build job's output did not be printed from user selected tray. |
| | Fix Defect | Scan to Email functionality improved. |
| | Fix Defect | Fix defect of CounThru issue. |
| | | 1. After Back up and Restore, Back up is not set(authorization. mode, application management) |
| | | 2. Fix a PCL6 error when print a A3 format by A4 size. |
| | | 3. Improve the delay to print a large sized PDF file. |
| | | 4. Wrong localized message for Communication Error string |
| | | 5. LDAP issues and Auto log out issue. |
| | | - Pre-fill issue, field [To] is not properly filled. |
| | Fix Defect | - Auto "logout time" doesn't works even if the time is expired, the UI never logged out automatically. |
| | | 6. If user login before AA initialization, UI does not work with "Please wait" message. |
| | | 7. [Print Driver] Install/Print Performance Enhancement. |
| | | 8. Disable screen shot capture after restore the item is already set to disable but needs. |
| | | 9. Printing a job with Chinese name from USB does not work. |
| | | 10. DNS does not work when IPv6 is enabled. |
| | | 11. Improve scan quality of original image with Watermark. |
| | | 12. Language combo is not appearing in EDC save properties window in Win XP environment In case of text converting scanning, it will not be possible to list the languages available to sav scanned document. |
| | | 13. Change Custom sized paper type of MP tray to show in Tray Confirmation popup after selecting it from Plain to other type. |
| | | 14. Korean fonts from Safari AirPrint spool files are broken. |
| | | 15. Fix the custom paper size to save and show in Tray confirmation popup and Tray Settings. |
| | | 16. Add translation of Development Unit on SWS |
| | | 17. Support 'Scan to SMB V3' protocol on Mac OS 10.10 |
| | | 18. Improve the printing time of A3 PDF file on MS Project. |
| | | 19. After power off using Power button on UI, FDI is not counted. |
| | | 20. Improve UI performance. |
| | | 1. All individual setups in the Android UI can save in a backup file. |
| | | 2. Add stamp position TOP_CENTER / BOTTOM_CENTER for Copy. |
| | | 3. Apply background image & guide text on FDI block screen. |
| | | 4. Display the status of Log-In. |
| | | 5. Add a confirmation prompt to exit service mode as well as for memory clear. |
| | | 6. Add 'host name' to pull down menu of home screen. |
| | | 7. Authentication for Entering "Apps" Menu. |
| | | 8. Add to show a warning against the status of HomeScreen Lock. |
| | | 9. Add the function to select Right / Left staple. |
| | | 10. Add Fax Send Confirmation report. |

| | I | 11. Add ID Send to box, but not to store in the USB device. |
|---------------------------------|--------------|---|
| | | 12. Support Scandic letters when scan to email. |
| | | 13. Support Hebrew and Arbic font in 4th GUI. |
| | Add Func. | 14. Support to select decreased image of first page on fax send report. |
| | ridd Fulle. | 15. Support SFE [032] - Line compensation for MS Excel. |
| N.F. C.C. 0.2 | | 16. Add QR code that contains Device related data on Settings App. (Settings -> About System |
| | | 17. Request to set Logout Confirmation popup to be enable or disable. |
| V5.C6.03 17-Apr-2015) | | 18. Add a feature to remove deactivated scan ID from UI. |
| 17-74p1-2013) | | |
| | | 19. Request to sort Korean alphabetically for Scan To Shared Folder list. |
| | | 20. Support 'o' search filter in LDAP search and LDAP authentication. |
| | | 21. Support Scan to FTPs. |
| | | 22. Homepage customization of UI and remote distribution. |
| | | 23. Support Confidential Print icon as XOA solution. |
| | | 24. Support PrinterOn solution by PAR. |
| | | 25. Request for default user profile for users who logged in through 3rd party solution. |
| | | 26. Request supplies coverage data display on solutions (SyncThru, PrintFleet) by using SET MIB information. |
| | | 1. Improve to be able to change the settings of the SMTP server through SWAS. |
| | | 2. Adjustable width on SmartSearch pop-up, when enter in Send to Email. |
| | | 3. Change the color for destination text in ScanWidget. |
| | | 4. Paper weights(g) are added with each paper type in the window of tray confirmation popup. |
| | | 5. Expand the number of characters in password for secure print. |
| | | 6. Change FaxWidget to be able to do another fax in processing. |
| | | 7. Change the method of showing Memory capacity (as Main+UI) |
| | | 8. Improve SWS Report feature view the printer report instead of printing to the printer. |
| | | 9. Change SPDS error code because are not same as the Device. |
| | | 10. Add new warning message not to turn off the device during FW upgrade |
| | | 11. Change to notify NFC FW Upgrade to users.12. Support a local card reader of China (same as MX4). |
| | | 13. Support to enable Application Authentication for Web Print application. |
| | | |
| | | 14. Change to save more that 20 of Machine ID&Fax numbers in Fax Setting. |
| | | 15. Expand LDAP Search max results from 300 to 500. |
| | | 16. Change to be disable to access PDF option if other file format except of PDF is selected in Scan&Send. |
| | CI C | 17. Change to use UCS file as base table of Smart Color Manager |
| | Change Spec. | 18. Admin password of many machines can be changable remotely at once. |
| | | 19. Disable manual input of email address on ScanToEmail. |
| | | 20. Add 480min as Power save time and disable Eco function. |
| | | 21. Implement Password validation to be handled in Send. |
| | | 22. Change ScanToFTP with configurable Communication Mode. |
| | | 23. Compatibility with HP UPD (Universal Printer Driver). 24. Change Network PC FAX to support 500 reciepents. |
| | | 25. Support Early Warm Up for fast printing. |
| | | 26. Support "Address Book -> Import" feature for both 'Append' and 'Overwrite'. |
| | | 27. Support multilanguage for creating Box - file/folder. |
| | | 28. Change the previous destination to clear after system timeout or if reset is pressed, although |
| | | "Keep Previous Destination" is on. |
| | | 29. [Print Driver] Support Custom Tray Mapping and Paper Based Watermark. |
| | | 30. Change the French translation from "Mon boite" to "MA BOITE". |
| | | 31. Remove the previous email address not to be remained in email address box to enter after using Scan & Send app. |
| | | 32. Change the German text from "Anwendungs mangement" to "Anwendungsmangement" in "UI->Settings->Application Management" menu. |
| | Delete Func. | 1. Remove Online Registration from SWS > Maintenance > Links. |
| | | After continous fax jobs are completed, Job window for showing the progress does not close |
| | Fix Defect | UI is pending or Firmware update is going slow intermittenly during booting. |
| V5.B6.22 | TIA DEICCI | 3. Wakeup failure from Power save mode intermittently. |
| 6-Mar-2015) | | 4. OPC Install Date Writing failure. |
| | | 5. [SWS]Copy -> Staple Selection & addressbook -> Group does not work properly. |
| | Change Spec. | 1. Separate Fax Send report from the common report. |
| | | 1. UI Black screen error during booting abnormally. |
| | F. D.C | 2. Toner value displaying issue. |
| | Fix Defect | |

| (16-Jan-2015) | | 4. Some ISV application does not started after rebooting machine. |
|--------------------------|---------------|---|
| | Change Spec. | Change UI Firmware to be compatible with eMMC of KingSton. |
| | Change Spee. | 2. Send usage counter is different from between Counter app and Usage counter information. |
| | | 1. Fix pending on fax receiving by pressing stop button. |
| | | 2. Fix send app crashing issue. |
| | Fix Defect | 3. Add the wholely delete button on Fax widget. |
| | | 4. Improve Scan to PC speed. |
| | | 5. Improve LDAP searching function. |
| | | 6. Fax printing on unidentified phone number. |
| | | 7. Private folder ID can set up upto 64 byte. |
| | | 8. Improve SMB scan function. |
| | | 9. Modify Google Cloud Printing resister. |
| | | 10. Improve line handling performance. |
| | | 11. Fix Store and Print issue. |
| | | 12. Fix Stop button issue on MP Tray. |
| | | 1. Add the button to delete task at once. |
| | | 2. Improve LDAP searching function. |
| | | 3. Support DFS (Distributed File System) option on SWS. |
| | | 4. Number keypad defaulted when PIN code log-in. |
| | | 5. Add saving option the created local user to address book. |
| | | 6. Add Scan Masking Area Adjuistment on Tech Mode. |
| | | 7. Add Send tap destination Adjustment. |
| | | 8. Support A5 size LEF printing. |
| | | 9. Add delete option for default application. |
| | | 10. Add function for playing video clip on USB memory. |
| | | 11. Add the function of WiFi / Active NFC. |
| | Add Func. | 12. Add Myfax option in +Me setting. |
| | Change Spec. | 13. Add sharing function on Box App. |
| | | 14. Add Index scrolling in address book. |
| | | 15. Support Scan to Me. |
| V5.B6.11 (14-Nov- | | 16. Add VNC fuction (Virtual Network Computing).17. Add Sharing function Send APP to other APPS. |
| 2014) | | 18. Support prefix dial on Fax widget. |
| , | | 19. Add Wi-Fi icon when connected. |
| | | 20. Add duplex printing option when printing in USB. |
| | | 21. Add option of Web print APP disable. |
| | | 22. Add Haptic function to all menu. |
| | | 23. Add Web address function of auto complet, progress bar, delete at once. |
| | | 24. Add the button to delete task at once. |
| | | Delete initial page on Copy shortcut. |
| | | 2. Initialize the copy option when click the Interupt during copying. |
| | | 3. Auto paper detection when using the scan widget. |
| | | 4. Copy APP's preview can change to Number keypad. |
| | | 5. Improve UX usability. |
| | | 6. Improve the searching usability of LDAP address book. |
| | | 7. Automatically destinate to USB when insert USB memory. |
| | | 8. Add extra stamp position. |
| | | 9. Enlarge the size of number on Fax widget. |
| | | 10. Home Screen Setting authorized by admin, not user. |
| | | 11. Always wake up the Panel during video clip play. |
| | | 12. Remain recipient after Scan and Send execute. |
| | | 13. Add enter the copies number function in Copy widget. |
| | | 14. Shows defaultly number keypad in Fax widget. |
| | | 15. Create single PDF/TIFF files by scan. |
| | | 16. Display lock image on Secure PDF. |
| | | 17. Admin has authorize to delete the private folder. |
| | | 18. Default color setting of Copy widget is syncronized with Copy APP. |
| | | 19. Email notification of Counter Report includes essitial contents. |
| | | 20. Reduce Scan noise. |
| | Delete Func. | 1. Remove user information from Logs. |
| | Defete Fulle. | 2. Remove "Ready to Copy" string placed on right bottom of Panel. |