

Firmware Release Note



Model: M5360 Series	Date: 24-June-2019
----------------------------	---------------------------

V5.A0.00.22 FW addresses total of 2 issues.

- Major Changes

1. Fixed, the fax not working while in power save mode.
2. Applied the new WLED for scanner.

Please upgrade the FW with V5.A0.00.22 if any one of the problems below need to be resolved.

Version	Category	TSP ID	Division	Change Description
V5.A0.00.22 (24-June-2019)	Requirement	-	-	Applied the new WLED for scanner.
	Problem	-	-	Fixed, the fax not working while in power save mode.

Software Component Versions

System Firmware	V5.A0.00.22
Main FW Version	V11.01.00.00.22_05-29-2019
XOA Web	1.4.8
UP	1.17.9_(20150813164608)
Engine Firmware	V0.00.57
File System Version	FS_V20.00.00.00.19
SCB(Scan,Fax) Version	V4.00.00.17 04-22-2019
Boot Rom Version	V20.10.00.00.38-02-13-2019
UI Firmware	V5.40.00.11.00_18101121
RADF Firmware	00.00.16
Finisher Version	M5360_FIN_1BIN_V5.05
HCF/SCF version	M5360_SCF_V3.1.9
Scan_Control	V0.25
Samsung Mobile Print	V11.23.02_170911
PCL5CE	V3.8.22_170906
PCLXL	V3.11.00.76_160613
PS/PDF/XPS	V3.6.01.01.60.01.93_160720

Image Quality Tables

EP	V2.29
Fuser	V2.90
Toner	V2.08
TR	V1.41
Print CMS	V1.0
Copy CMS	V1.3.190107
Scan CMS	V0.16
Print IEM	V0.2
Copy IEM	V0.42

Update dependency

N/A

Solution Compatibility Table

(M5360 : V5.A0.00.22)

Category	Solution Name	Solution Version	V5.A0.00.22	Verified F/W Version
BCPS	CloudConnectorCore	2.50.006	○	V5.A0.00.18
	DocumentWorkflowCore	2.50.006	○	V5.A0.00.18
	PrintingSecurityCore	2.50.006	○	V5.A0.00.18
	SecureLoginCore	2.50.006	○	V5.A0.00.18
	UsageTrackerCore	2.50.006	○	V5.A0.00.18
ISV-XOA-E	Equitrac	1.1.0.136 (Server : 5.6.25.5109)	○	V5.A0.00.14
	Omtool AccuRoute	1.0.0.689 (Server : 2013(Build 5))	○	V5.A0.00.14
	PaperCut	1.0.33918 (Server : 16.0 (Build 35320))	○	V5.A0.00.14
	PrintFleet Cloud Embedded DC	1.0.249	○	V5.A0.00.14
	Ringdale FollowMe	1.1.2.9 (Server : 6.1.0.103)	○	V5.A0.00.14
	SafeCom	010.24.23 (Server : S82070.520*10)	○	V5.A0.00.18
	SafeQ Embedded Terminal	1.0.0 (Server : 5.0.4)	○	V5.A0.00.14
	Scanner Vision	1.0.6 (Server : 6.2.0.270)	○	V5.A0.00.14

	Scanshare Essentials	1.5.17.169 (Server : 4.4.0.5)	○	V5.A0.00.14
	Ubiquitech Easy & VDMS	1.5.2-rel3 (Server : 4.0.0)	○	V5.A0.00.14
PrinterOn	PrinterOn Branded Agent	2.03.003	○	V5.A0.00.18

- ◎ A solution has been verified and MUST be compatible with the releasing F/W version.
○ Previously the supported solutions have been tested and verified with the version specified in the "Verified F/W version" row in the table.
The required test has been conducted on this FW version to ensure the backward compatibility with "Verified F/W version".

Release History

Version	Category	TSP ID	Division	Change Description
V5.A0.00.21 (7-Mar-2019)	Problem	-	-	Fixed to support the GCP uses latest google specified certificates.
	Problem	-	-	Fixed the performance mode power save mode to avoid HDD disk failure.
	Problem	-	-	Fixed SMTP to work even when server supports only TLSv1.2
	Problem	-	-	Fixed, when snmpcommunity.cgi is called SNMPv3 is getting disabled issue.
	Problem	-	-	Fixed the WSD Install issue in Win10 for a specific version.
	Problem	-	-	Fixed the Google Address Book issues
	Problem	-	-	Fixed the Memory issue with mDNS
	Problem	-	-	Fixed the issue of Box app Authentication.
V5.A0.00.18 (28-Sep-2017)	Requirement	-	DEV	The Blue Angel 2017 ready
	Fixed issue	TP16A0E430	SEBN	Fixed an issue of printing data being corrupted from PC usb cables when the machine sleeps
	Fixed issue	-	DEV	Fixed the issue of failing to print out stored jobs including outbin and finishing option
	Fixed issue	-	DEV	Fixed the issue of failing to activate license when only setting up SSL option without specifying SSL port at the license server address
V5.A0.00.16 (16-May-2017)	Fixed issue	TP1740K7	SECA	Fixed "U2-1113", a kind of LSU Error, which can happen when printing from sleep mode.
	Requirement	-	DEV	Optimized how to recognize the environment around the machine with a new humidity sensor table
	Fixed issue	TP16502A	KOREA	Improved the issue of the system slowing down in DHCP mode without DHCP serverconnection
V5.A0.00.15 (25-Aug-2016)	First version	-	-	First release