Firmware Release Note

Model: X7600 Series Date: 18-Dec-2019

V6.H6.00 FW addresses total of 7 issues.

- Major Changes
- 1) Removed the functionality to print the barcode.
- 2) Fixed, Custom size 450X298mm printing in duplex mode.
- 3) Fixed, inner finisher folding and not stapling the last page when printing odd number of copies issue.
- 4) Fixed, the upper finisher issue for A3 duplex printing.
- 5) Fixed, the network print issue after soft reboot.
- 6) For Gov models, the A4 Demo page is changed to add more information.
- 7) Fixed, the SNMP OID status for HCF tray to display it on the panel.

Please upgrade the FW with V6.H6.00 if any one of the mentioned problems need to be resolved.

| Version | Category | TSP ID | Division | Change Description |
|--------------|----------|--------|----------|--|
| | Problem | | KOREA | Removed the functionality to print the barcode. |
| | Problem | | KOREA | Fixed, the SNMP OID status for HCF tray to display it on the panel. |
| | Problem | | KOREA | Fixed, the network print issue after soft reboot. |
| V6.H6.00 | Problem | | KOREA | Fixed, Custom size 450X298mm printing in duplex mode. |
| (2019-12-18) | Problem | | IKOREA | Fixed, inner finisher folding and not stapling the last page when printing odd number of copies issue. |
| | Problem | | KOREA | Fixed, the upper finisher issue for A3 duplex printing. |
| | Problem | | KOREA | For Gov models, the A4 Demo page is changed to add more information. |

Software Component Versions

| Software Component Versions | |
|-----------------------------|----------------------------|
| System Firmware | V6.H6.00 |
| Main FW Version | V11.01.10.00_09-20-2019 |
| XOA Web | 1.4.33 |
| UP | 1.17.34_(20171218171009) |
| Engine Firmware | V2.02.67 04-11-2019 |
| File System Version | FS_V15.02.06.23.15 |
| SCB(Scan,Fax) Version | V3.00.05.05 03-25-2019 |
| Boot Rom Version | V15.11.00.00.07-09-18-2019 |
| UI Firmware | V5.18.50.12.00_19040115 |
| ADF Firmware | 00.03.60 |
| Trayl | V2.02.67 |
| Tray2 | V2.02.67 |
| Tray3 | V02.21.00 |
| Tray4 | V02.21.00 |
| finisher(Inner) Version | V01.56 |
| finisher(3K) Version | V02.67 |
| Booklet Version | V02.33 |
| Hole Punch Version | V04.06 |
| PCL5CE | V8.22_170906 |
| PCLXL | V11.00.90 |
| PS/PDF/XPS | V6.21.01.62.02.03_170415 |

Image Quality tables

| mage Quanty tables | |
|--------------------|--------------|
| EP | V4.01 |
| Fuser | V5.74 |
| Toner | V3.25 |
| TR | V1.64 |
| Scan Control | V0.50 |
| Print CMS | V13.03.10.10 |
| Copy CMS | V.13.02.0818 |
| Scan CMS | V2.4 |
| Print IEM | V0.36 |
| Copy IEM | V6.50.1219 |

Solution Compatibility Table (X7600 : V6.H6.00)

| Category | Solution Name | Solution Version | V6.H6.00 | Verified F/W Version |
|-----------|------------------------------|---|----------|-------------------------|
| | CloudConnectorCore | 2.50.008 | 0 | |
| | DocumentWorkflowCore | 2.50.007 | 0 | |
| BCPS | PrintingSecurityCore | 2.50.009 | 0 | |
| BCFS | SecureLoginCore | 2.50.006 | 0 | |
| | UsageTrackerCore | 2.50.007 | 0 | |
| | XOA-WEB Enabler | 2.00.003 | 0 | V6.D6.29 |
| | Autostore | 1.0.0 (Server : 7.00.3.0 (DRS:7.0.1.16, APD:7.0.3.26)) | 0 | V6.E6.05.02.071317 |
| | Drivve Image | 1.5.43 (Server : 5.1.546) | 0 | V6.A2.54 |
| | Drivve Print | 1.1.30 (Server : 3.1.100) | 0 | V6.A2.54 |
| | Equitrac | 1.1.0.135 (Server : 5.2.21.8778) | 0 | V6.D6.29.03.120609 |
| | Geniusbytes MyMFP | 2.19.6.2 (Server : 2.19.3) | 0 | V6.G6.02.02.050715 |
| | NDDigital n-Access | 2.1.3 (Server : NDDigital n-Billing 4.9) | 0 | V6.D6.07 |
| | NDDigital n-Collector | 2.2.4 (Server : NDDigital n-Billing 4.9) | 0 | V6.D6.07 |
| | NDDigital n-Releaser | 2.1.4 (Server : NDDigital n-Billing 4.9) | 0 | V6.D6.07 |
| | Omtool AccuRoute | 1.0.0.689 (Server : 2013(Build 5)) | 0 | V6.D6.07 |
| ISV-XOA-E | PaperCut | 1.1.0 (Server : 16.4 (build 38954)) | 0 | V6.F6.01 |
| | PrintFleet Cloud Embedded DC | 1.1.249 (Server : 3.6) | 0 | V6.E6.05.02.071317 |
| | Ringdale FollowMe | 1.1.2.9 (Server : 6.1.0.103) | 0 | V6.D6.07 |
| | SafeCom | 010.24.23 (Server : 10.520.10.35) | 0 | V6.F6.04.03.101119 |
| | SafeQ Embedded Terminal | 1.0.0 (Server : C.0.18.002) | 0 | V6.D6.29.03.120609 |
| | Scanner Vision | 1.0.6 (Server : 6.2.0.270) | 0 | V6.D6.07 |
| | Scanshare Essentials | 1.5.15.167 (Server : 4.0.5) | 0 | V6.D6.07 |
| | Ubiquitech Easy & VDMS | 1.5.3-rel3 (Server : 5.0.0-rel [ca91b]) | 0 | V6.D6.29.03.120609 |
| | e-Paper Sentinel | 5.0.7 | 0 | V6.D6.07 |
| | Prism ScanPathTM | 1.0.49 (Server : 2.5.0.29) | 0 | V6.A2.18 |
| SmartUX | Nuance unified client | 1.0.0.606 (Server : 5.7.28.6490(CAS:5.7.28.6490, APD : 7.0.4.0)) | 0 | |
| PrinterOn | PrinterOn Branded Agent | 2.03.003 | 0 | V6.F6.04.03.101119 |

① A solution has been verified and MUST be compatible with the releasing F/W version.

FW Release History

| Version | Category | BTSP ID | Division | Change Description |
|--------------|----------|---------|----------|---|
| | Problem | | KOREA | Fixed, XSS weak point of Samsung models. |
| | Problem | | KOREA | Fixed, slow UI and slow copy feature. |
| | Problem | | KOREA | Fixed, IPv6 manual address for fdxx as prefix. |
| | Problem | | KOREA | Fixed, S5-3116 if no hardware failure. |
| | Problem | | KOREA | Implementation of new requirement to enhance the SWS security. |
| | Problem | | KOREA | Added more flexible configuration to control device quota. |
| | Problem | | KOREA | Fixed the IDCopy parameter getting reversed while submitting of job. |
| V6.G6.02.02. | Problem | | KOREA | Fixed, to print all documents in queue from BCPS when documents come from MacOS. |
| 050715 | Problem | | KOREA | Fixed, MX7 WTB drive motor's torque margin. |
| (2019-05-30) | Problem | | KOREA | Fixed, the fax not working while in power save mode. |
| | Problem | | KOREA | Fixed, conflict between Front Back in Cover and Fold Staple in Booklet. |
| | Problem | | KOREA | Fixed the issue of device going to home screen after login using GeniusMFP solution. |
| | Problem | | KOREA | Fixed, Manual Reset of device quota reset policy. |
| | Problem | | KOREA | Fixed, android security issue for password field. |
| | Problem | | KOREA | Fixed the print output order. |
| | Problem | | KOREA | Fixed, wrap jam information in fuser eeprom. |
| | Problem | | KOREA | Fixed, inner finisher jam issue with punch option. |
| | Problem | | KOREA | Thai translation for Wrap Jam Error(M2-1317) is updated. |
| (2019-01-21) | Problem | | KOREA | UI Slowness issue is fixed. |
| | Problem | | KOREA | Fixed the issue that image log not sent to Printing Security Solution Server when fax images recieved through Line2 |
| | Problem | | KOREA | Improved Fusing mechanism for Fuser wrap JAM |

O Previously the supported solutions have been tested and verified with the version specified in the "Verified F/W version" row in the table. The required test has been conducted on this FW version to ensure the backward compatibility with "Verified F/W version".

| V6.F6.04.03. | Problem | | DEV | Fixed Firmware update failure or blank image scanning could be happened when Host Name contains "VE" |
|---|-------------|------------------------|------|--|
| 101119 (2018-11-01) | Problem | | DEV | Fixed the issue of WSD Print installation with Win10 (1703/1709/1803) |
| (| Problem | | DEV | Fixed the Google Address Book stay signin issue and showing previous user contacts |
| | Problem | SIE174695 | EMEA | Fixed the issue of Box app Athentication |
| | Problem | 312174093 | DEV | Fixed MFP slow down issue with mDNS |
| | | SIP68753 | | |
| | Problem | TP174000 | EMEA | S1-2452 Error issue was fixed by improving the DB recovery logic |
| | Problem | | DEV | When SNMP Community Web Service is called via HPSM application to add/edit/delete the community names, a side effect is observed that SNMPv3 is getting disabled. This side effect is fixed |
| V6.F6.04.02. | Problem | SIP68582 | AMS | Fixed SMB 2/3 job failed issue due to excessive permissions requested |
| 072419 (2018-08-01) | Requirement | | DEV | SNI(Server Name Indication) is added by new requirement for Google Cloud Print servers when SSL enabled. |
| | Requirement | | DEV | New feature implementation for configurable 'SSL/TLS' protocols and ciphers option. Security level configuration can be done according to user requirement from SWS. |
| | Problem | SIE173360 | EMEA | Fixed booklet fold & staple option is not working when printing mulple copies from stored job |
| | Problem | | SQE | The Punch option doesn't take effect after changed it from 2Punch to 4Punch under Box->Print->print options. This is fixed |
| | Problem | TP1790KD | SEAU | Error 403' caused when connecting to Google Addressbook due to Google policy changes is fixed. |
| V6.F6.04.01. 041619 (2018-05-04) | Problem | - | DEV | The intermittent stoppage caused when creating Hibernation Image when https is enabled is fixed. |
| | Problem | - | DEV | Inaccurate range value associated with Scan background density from Nuance Unified client compatibility test is fixed. |
| | Problem | TP17A06W | SEA | The issue that file stored at Box App is not intermittently deleted at the device where HDD Image Overwrite is enabled is fixed. |
| | Problem | SIP65410 | SEG | The issue that Ext.Phone setting in service mode revert back to initialized value when dual Fax card is installed and power cycled is fixed. |
| | Problem | - | SEBN | Login speed has improved when using Nuance Unified client. |
| | Problem | SIP65701 | SEG | The issue that certificate related setting value is reset as default after changed F/W version including updated Send App is installed is fixed. |
| | Problem | SIP64544 | SEAU | The issue that fuser detection fails due to intermittent timing in case that a user sends a job when the device enters sleep is fixed. |
| | Problem | SIE154757 SIE156425 | SAU | The issue that email is not delivered under ScantoEmail in case that special characters(ex) ',') are included in sender's user name is fixed. |
| | Requirement | SIE157066 | EMEA | New certificate of Google Cloud server is applied. |
| | Problem | - | SEG | Copy sharpness value change failure on FAP is fixed. |
| | Problem | - | EMEA | Special characters except for '<' and '>' are now allowed as LDAP server access password. |
| V6.F6.04 (2018-02-12) | Problem | - | KOR | Change to define start and end time when enabling performance optimization feature. |
| <u>, , , , , , , , , , , , , , , , , , , </u> | Problem | - | SEG | Fixed an issue of unintended color being printed because of wrong processing of 1x1 size pattern in PCL5 job for color printers. |
| | Problem | - | KOR | Fixed an issue of black text printed as white in specific application for color printers. |
| V6.F6.01 (2017-10-27) | | TP17801L | SEBN | Fixed an issue of the reset database menu being displayed at booting phase by intermittent corruption of audit database index. |
| | Requirement | - | SEF | LUI default screen is changed to Kiosk home screen when FDI and Smart Printing Kiosk app are used together. |
| | Problem | TP1720J901 | KOR | Allow Korean characters in the Scan to SMB path. |
| | Problem | TP173078 | SEUK | 1 sheet booklet and folding printing job, which can have 1~4 pages original document, is able to fold with Heavyweight media. - X4300, K4350: Thick, Heavyweight, Thin Glossy - X7600, K7600: Thick, Heavyweight, ExtraHeavyweight1, ExtrayHeavyweight2 - Driver: UPD 3.00.13.00:03 |
| | Problem | - | DEV | Fixed an issue of iterated login and logout when performing NFC authentication on device, WIFI/NFC module(SL-NEW001X) installed, with the latest cellular phones such as Galaxy S8. |
| | Problem | TP1720K8 | SECA | Fixed an issue of scanned images being right shifted when scanning MSO(Mixed Size Original) |
| V6.E6.09.04. 090410 | Problem | TP1740C3 | SEA | Fixed an issue of slow booting or WIFI disconnection when power cycled by soft power button on UI when WIFI/Bluetooth (BLE, Bluetooth Low Energy) module(SL-NWE002X) installed. |
| (2017-09-20) | Problem | TP174000 | SEUK | Improve DB(Database) error recovery routine for damaged record only instead of DB initialization. |
| | | | 1 | |

| i i | | 1 | | 1 |
|--|-------------|----------|-------|--|
| | Problem | TP1750JO | SEAU | Fixed an issue of a scan job being stopped when adding a document while the last document comes out during the ADF scanning. |
| | Problem | TP176005 | SEI | Fixed an issue of the memory clear button in the service menu not being activated after power on but intermittent exception occurred in WSD initialization. |
| | Problem | TP1750OA | SEG | Allow compact PDF option in XOA-E API for ISV solutions. |
| | Problem | TP177025 | SEHK | Fixed an issue of a Fax Rx job pending when all received pages can not be decoded by corrupted data. |
| | Requirement | - | DEV | The Blue Angel 2017 ready. |
| V6.E6.09 | Problem | TP17607P | SEG | Fixed an issue of not being able to use a device as MSOK errors occur intermittently under certain conditions while enabling HDD encryption function and using the device. |
| (2017-09-20) | Problem | TP17607P | SEG | Fixed an issue of F/W update failure in the certain F/W version because of boot memory space shortage(Refer to 2017_CMFP-012_guide_for_FW_update_error_61-1H05). |
| | Problem | TP16C0JD | SEIL | Fixed an issue that the destination of Scan Widget was displayed as None after the Scan Widget was terminated abnormally. |
| | Requirement | TP1710KL | SEASA | A new API was provided to hide buttons on the navigation bar of UI such as back/home button. |
| | Requirement | TP1730AG | SEPOL | Remove destination email address in the PDF file generated from Scan to email. |
| | Problem | МКТ | SEA | Fixed a problem where the Hole punch menu was not visible in the Copy App when Hole punch unit is installed later after installing the Finisher. |
| | Problem | TP17309T | SEA | Fixed an issue where color copier with booklet finisher got outbin full while printing B/W booklet job, sometimes the job was not resumed even after the outputs were removed. |
| | Problem | TP1710JX | SEG | Fixed an issue where one of continous printing jobs was not printed intermittently due to |
| | Problem | TP1670LC | SEA | Added a new settings which specifies a default folders of Box App. * Box App > Action Overflow(3 dot button) > Box Settigns > Default Display Folder |
| V6.E6.05.02. 071317 | Problem | - | DEV | Fixed an issue that sometimes a job was not canceled and remained cancelling state until rebooting. |
| (2017-07-26) | Problem | TP1740DR | SEUK | Fixed an issue that when a large number of print jobs were saved in the Box, some of jobs were not printed by Print & Delete function for all jobs. |
| | Problem | TP1730IK | SEGR | Fixed an issue when a double-sided job was printed from DCF with half-speed feeding by paper weight such as Thick, Extra Heavyweight paper type, sometimes double-sided pages were printed with unexpected order. |
| | Problem | TP1750CC | SEG | Fixed an issue of stripped patterns on the part of image of PCL5 job which consists of mono data and color macro data. |
| | Problem | TP1750I4 | SEA | Fixed an issue where the finishing option was cleared to default when printing a saved booklet job in the Box app with changing 'copies' option. |
| | Problem | TP17600R | SEG | Fixed an issue where finishing option is cleared to default when the job was rescheduled by pape mismatch/empty. |
| | Problem | TP17607P | SEG | Fixed system failure case by intermittent MSOK error when HDD encryption is enabled. |
| | Requirement | TP1670QW | SEA | Added Bates Numbering feature to the copy app. Prefix, Suffix, and Number of Digit (up to 9 digits) settings are added to the Copy > More > Stamp menu |
| | Problem | TP16802X | SEA | Fixed an issue of setting value reset when program was executed after setting a booklet option in a copy app and creating the program. |
| | Requirement | TP16A0SB | SEUK | Added a Jam Count Rreset feature to the service mode. |
| | Problem | TP16B0KD | SEG | Fixed an issue where the separator page was stapled together with the original printout when |
| | Problem | TP16C0JQ | SEA | Populate recipient name in front of "From" email address at the Scan to email function. ex) As-Is: From: <sghj@ghj.com> To-Be: From: "ghjeong" <sghj@ghj.com></sghj@ghj.com></sghj@ghj.com> |
| | Problem | TP16C003 | SEG | Fix an intermittent issue that partialy damaged PDF file is generated by color scanning with |
| | Problem | TP171017 | SEA | Fixed not to staple every single page for multiple printing of one page. |
| | Requirement | TP16909R | SEBN | Supported a special character \\' in the LDAP search option. |
| | Problem | TP16C0EG | SECH | Added a function to automatically fill user email address registered in the job account (JAC) in recipients when logging in and running Scan & Send App. |
| V6.E6.05.01. 042409 (2017-05-08) | Problem | - | DEV | Even an user changes filename format of Scan&Send > Scan Options > Filename, real date & time will be used if it still has Dates&Time format, such as DDMMYY. ex) As-Is: test_DDMMYY saved as "test_DDMMYY" To-Be: test_DDMMYY will save as "test_100517" |
| | Problem | TP1710MR | SEA | Switch to fax sending job by deleting email address when entering fax numbers if email was already put as a recipient at the Scan & Send app. |
| | | 1 | 1 | Fixed an issue that remaining error handling videos were not displayed when one of the |

| Problem Proble | II | T | ı | 1 | |
|--|--------------|----------------|---------------|-------|---|
| Requirement IP186000 SUK Added a function to select and take address directory from LDAP. | | Problem | - | DEV | Fixed the black and white scan counts to be increased for scanning job with setting the color mode to the mono. |
| Problem TP17306W SEG Sixed in sectar an item from 1DAP result when Server tab is set as default at Scan & Send approaches directory function. | | | - TP1660L0 | | 1 1 1 1 1 1 |
| Problem Proble | | - | | | · |
| Problem P17105G SEN directly from USB, the output of the character spacing widehed or an error occurred so that the output was not printed. | | Problem | TP1730EW | SEG | address directory function. |
| Problem P1730KE KOREA Fix an error in PDF direct printing by abnormal font data included in the PDF file which is generated by specific PDF created application. Problem DeV Fixed an issue of filtering an -mail as junk mail on Gmail server if the default message was used Problem DeV Fixed an issue of displaying devices with the same MAC address at the default message was used Problem Fixed an issue of intermittent finisher jame IDF MAC address at the palmacycle definite R4 media and A3 fixed gas Problem Fixed an issue of intermittent finisher jame IDF MAC and the part of the part of the problem Fixed an issue of intermittent finisher jame IDF MAC and the part of the part of the part of the problem Fixed an issue of intermittent finisher jame IDF MAC and the part of the part of the problem Fixed an issue of intermittent finisher jame IDF MAC and the part of the part of the problem Fixed an issue of intermittent finisher jame IDF MAC and the part of the problem Fixed an issue of intermittent finisher jame IDF MAC and the part of the problem Fixed an issue of intermittent finisher jame IDF MAC and the part of the problem Fixed an issue of intermittent finisher jame IDF MAC and the part of the problem Fixed an issue of intermittent disappearance of PC list by DB corruption when using Scan to PC Fixed an issue of unworked SFE behaviors when applying SFE27, SFE34 stup at issued to problem Fixed an issue of unworked SFE behaviors when applying SFE27, SFE34 stup at issued Fixed an issue of unworked SFE behaviors when applying SFE27, SFE34 stup at issued Fixed an issue of unworked SFE behaviors when applying SFE27, SFE34 stup at issued Fixed an issue of unworked SFE behaviors when applying SFE27, SFE34 stup at issued Fixed an issue of unworked SFE behaviors when applying SFE27, SFE34 stup at issued Fixed an issue of unworked SFE behaviors when applying SFE27, SFE34 stup at issued Fixed an issue of unworked SFE behaviors when applying SFE27, SFE34 stup at issued Fixed a | | Problem | TP1710GG | SEBN | directly from USB, the output of the character spacing widened or an error occurred so that the |
| Problem Prob | | Problem | - | DEV | Improve double-sided printing speed of Executive paper size. |
| Problem DEV Fixed an issue of displaying devices with the same MAC address at Fleet Admin Prob device its Problem OEV Fixed an issue of intermittent (insight gelevat at third principle) Problem | | Problem | TP1730KE | KOREA | |
| Problem OREA Fixed an issue of intermittent fixing defect at thinplain recyclesthick St media and A3 fedger Problem P1710BP SEA Fixed an issue of internitutent fixing defect at thinplain recyclesthick St media and A3 fedger Problem P1710BP SEA Fixed an issue of intitializing Job accounting setup info. created at Fleet AdminPro when rebooting the device at SWS or Fleet AdminPro Froblem P1710BP SEA Fixed an issue of initializing Job accounting setup info. created at Fleet AdminPro when rebooting of the device at SWS or Fleet AdminPro Fixed an issue of admin password change as default when challing SFE 019 function at issued report and device at SWS or Fleet AdminPro Fixed an issue of admin password change as default when challing SFE 019 function at issued import and device setting backup (cloning) when using address book to register destination information disappears at program execution after address book in report and device setting backup (cloning) when using address stored in Adress book to register destination of program. Problem P1670UW SEI Adv T. L. Yer Other Order and in password change as default when challing SFE 019 function at sixuation and program. P1710Fe00 SEA Adv T. L. Yer Other Order and program P1710Fe00 SEA Adv T. L. Yer Other Order and program P1710Fe00 SEA Adv T. L. Yer Other Order and program P1710Fe00 SEA Adv T. L. Yer Other Order and print function at Scan to SMB feature. | | | TP16C0KM | | - · |
| Problem DEV Fixed an issue of intermittent finisher jammfLP-7928, HL-7939, when switching an engine mode Pix7070 Pix708P SEDA Pix6070 Pix708P SEDA Pix6070 SEDA Pix6070 SEDA Pix6070 SEDA Pix6070 SEDA Pix6070 SEDA Pix608P Pix6 | | | - | 1 | |
| Problem Prior Pr | | | - | | 1 1 1 |
| Problem P16707Q SEDA Pixed an issue of untitatizing float accounting setup into. created at HeelAdmini/Pox behaviors when the device at SWS or HeelAdmini/Pox Problem Problem SFE Rixed an issue of automated SFE behaviors when applying SFE27, SFE54 setup at issued Problem Probl | V6 E6 05 | Problem | - TD1710DD | | Fixed an issue of intermittent finisher jam(H2-7928, H2-7503) when switching an engine mode |
| Problem - SPE A SPEA in Issue of intermittent disappearance of PC list by DB comption when using Sea to DEV Problem - SPE A sea in size of admin password change as default when enabling SFE 019 function at issued import and device setting backup (cloning) when using address store) and affects book import and device setting backup (cloning) when using address store) affects and affects and affects and affects and affects and affects affects are setting value when creating a program. Problem TP1670LU SEI Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEI Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEI Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Add Umlant charset to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Invariance and Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Invariance and Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Invariance and Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Invariance and Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Invariance and Add * [.] .** to the folder name input function at Scan to SMB feature. Problem TP1680HV SEA Invariance and Add * [.] .** to the folder name | II | Problem | TP16707Q | SEDA | |
| Problem DEV Fixed an issue of admin password change as default when enabling SPE 019 function at issued Problem TP1670L0 SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep the mixed size setting value when creating a program. Problem TP1670L0 SEA Add "[], "* to the folder name input function at Scan to SMB feature. | | Problem | - | | Fixed an issue of intermittent disappearance of PC list by DB corruption when using Scan to PC. |
| Problem TP1670DJ SEA Import and device setting backup (cloning) when using address stored in Adress book to register destination of program. Problem TP1670LQ SEA Allow mixed size to be default for original size value in the Copy / Send App, and keep the mixed size setting ballow hen reading a program sexecution after address book to register destination of program. Requirement SEUK Fax paper source tray setting is added to SWS. Problem TP1680HV SEI Add "[,]. "" to the folder name input function at Scan to SMB feature. Problem TP1690AR SEA Add Unimate character to the folder name input function at Scan to SMB feature. Problem TP1690AR SEA Add Unimate character to the folder name input function at Scan to SMB feature. Fix issues at Air print - Cornect a problem where the Duplex option didn't work at URF mode Fix an issue where portrait and landscape alternate when printing the same document intermittently. Problem TP16A0BS SEA Fix a problem where the Duplex option didn't work at URF mode Fix an issue where portrait and landscape alternate when printing the same document intermittently. Problem TP16B0BS SEA Fix a problem where the Duplex option didn't work at URF mode Fix an issue where portrait and landscape alternate when printing the same document intermittently. Problem TP16B0BS SEA Fix an issue where the machine reboots when using small paper that is not supported by DSDF. Problem TP16B0BS SEA Fix an issue where the machine reboots when using an areame it after the saving is Correct the problem displayed in the error report when the same tray for the saving is Cornect the problem displayed in the error report when the Sea Problem TP16B0BS SEC Fix an issue where 1AC enable / disable do not work by by the paper tray is open. Problem TP16B0BS SEC Fix an issue where 1AC enable / disable do not work by 190 problem. Problem TP16B0BS SEC Fix a problem that causes the device of freeze when the scanned image is skewed from the Problem TP16B0BS SEC Fix an problem that certain SFE functions are turne | | | | | |
| Problem TP1670LQ SEA import and device setting backup (cloning) when using address stored in Adress book to register destination of program. Requirement - SEUK Fax paper source tray setting a program. Requirement - SEUK Fax paper source tray setting is added to SWS. Problem TP1670LW SEI Add "I_I_N" to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Cornect a problem where the Duplex option didn't work at URF mode. - Fix issues at Air print - Cornect a problem where the Duplex option didn't work at URF mode. - Fix issues at Air print - Cornect a problem where the Duplex option didn't work at URF mode. - Fix issues at Air print - Cornect a problem where the Duplex option didn't work at URF mode. - Fix issues where portrait and landscape alternate when printing the same document intermittently. Problem TP16801S SEA Fax problem where the machine reboots when using small paper that is not supported by DSDF. Problem TP16801S SEBN Cornect the problem displayed in the ernor report when the Shi paper ray is open. Problem TP16801S SED Cornect the problem displayed in the ernor report when the Shi paper ray is open. Problem TP16800S SEB Cornect the problem displayed in the ernor report when the Shi paper ray is open. Problem TP16800N SEF Fix an issue where D4AC enable? disable do not work by job type via Pfeet Admin Pro. Problem TP1680NS SEF Fix an issue where the total sear page is incorrectly displayed is skewed from the Fix ap retiblem that causes the device to freeze when the scanning es is skewed from the Example of the Shi paper ray is open. Problem TP1680NO SEB Fix an issue where the total sear page is incorrectly displayed are swent paper ray is open. Problem TP1680NO SEA Cornect the problem that causes the device to freeze when the scannega is skewed from the Fix ap retible many and the paper ray is open. Problem TP1680NO SEA Cornect the problem that causes the devi | | Problem | - | DEV | Fixed an issue of admin password change as default when enabling SFE 019 function at issued |
| Requirement SEUK Fax paper source tray setting value when creating a program. | | Problem | TP1670DJ | SEA | import and device setting backup (cloning) when using address stored in Adress book to register |
| Problem TP1670UW SEI Add "[,], ^* to the folder name input function at Scan to SMB feature. Problem TP1680HV SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. - Fix an issue where portrait and landscape alternate when printing the same document intermittently. Problem - DEV Improve G3 fax transmission / reception quality and retry job protocol in VoIP environment. Problem TP168017 SEG Use a temporary file name while scaning and saving the file, and rename it after the saving is Problem TP168018 SEA Fix a problem where the machine reboots when using small paper that is not supported by DSDF. Problem TP168018 SECA Fix an issue where 21A cenable / disable do not work by job type via Fleet Admin Pro. Problem TP16800N SEI Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16800N SEF Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16800N SEF Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16800N SEF Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16800N SEF Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16800N SEF Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16800N SEF Fix a first stop when setting the Compact PDF option and changing color setting to Mono in Easy setting during scan. Problem TP16800N SEA Correct the problem that certain SFE functions are turned off after HDD recovery. Add HDD defect check function in HDD recovery mode screen. Problem TP1680N SEG Fix the problem where scan data transfer is slowed down for a sync problem when the area lot Problem TP1680VF SEA Fix the problem where scan data transfer is slowed down for a sync problem when the scanned in the problem Fix | | Problem | TP1670LQ | SEA | |
| Problem TP1690LW SEI Add "f.j.," To the folder name input function at Scan to SMB feature. Problem TP1690AR SENA Add Umlaut charset to the folder name input function at Scan to SMB feature. Fix issues at Air print - Correct a problem where the Duplex option didn't work at URF mode. - Fix an issue where portrait and landscape alternate when printing the same document intermittently. Problem TP1680BS SEA Fix an issue where portrait and landscape alternate when printing the same document intermittently. Problem TP1680BS SEA Fix a problem where the machine reboots when using small paper that is not supported by DSDF. Problem TP1680BT SEG Use a temporary file name while scanning and saving the file, and rename it after the saving is Problem TP16B0BN SED Correct the problem displayed in the error report when the 5th paper tray is open. Problem TP16B0DN SEI Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0DN SEF Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0DN SEF Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0DN SEF Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0DN SEF Fix a problem that causes the formance degradation when using counter widget. Problem TP16B0DN SEF Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0DN SEF Fix a problem that creatin SFE functions are turned off after HDD recovery. Requirement SEG Fix the problem that certain SFE functions are turned off after HDD recovery. Requirement SEG Fix the problem where scan data transfer is slowed down for a sync problem when the are a lot Problem TP16B0DN SEF Fix device stop when setting double-sided, 400% sendange option in Corpy job. Problem TP16B0DN SEF Fixed the error page not being printed above andrago option in Corpy job. Problem TP16B0DN SEAN Fixed the Searcheable PDF | | Requirement | - | SEUK | |
| Problem TP1690AR SEA Fix issues at Air print | | • | TP1670UW | SEI | Add "[,], ^" to the folder name input function at Scan to SMB feature. |
| Problem TP1690AR SEA -Correct a problem where the Duplex option didn't work at UKF mode. Fix an issue where portrait and landscape alternate when printing the same document intermittently. Problem - | | Problem | TP1680HV | SENA | Add Umlaut charset to the folder name input function at Scan to SMB feature. |
| Problem TP16A0B5 SEA Fix a problem where the machine reboots when using small paper that is not supported by DSDF. Problem TP16B017 SEG Use a temporary file name while scaning and saving the file, and rename it after the saving is SEBN Correct the problem displayed in the error report when the 5th paper tray is open. Problem TP16B01X SEPOL Fix a problem displayed in the error report when the 5th paper tray is open. Problem TP16B01X SEPOL Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0DN SEF Fix a ni issue where the total sent page is incorrectly displayed in the fax sent report when Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0DN SEF Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0DN SEF Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix a problem that causes the device to freeze when the scanned image is skewed from the Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix an issue standard transfer is slowed down for a sync problem Fix an issue standar | | Problem | TP1690AR | SEA | - Correct a problem where the Duplex option didn't work at URF mode Fix an issue where portrait and landscape alternate when printing the same document |
| Problem TP168017 SEG Use a temporary file name while scaning and saving the file, and rename it after the saving is | | Problem | - | DEV | Improve G3 fax transmission / reception quality and retry job protocol in VoIP environment. |
| Problem TP1680JS SEBN Correct the problem displayed in the error report when the 5th paper tray is open. Problem TP16B0IT SECA Fix an issue where JAC enable / disable do not work by job type via Fleet Admin Pro. Problem TP16B0LX SEPOL Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0SM SEF Fix a problem that causes performance degradation when using counter widget. Problem TP16B0SM SEF Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Froblem TP16B0SM SEF Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Froblem TP16B0SM SEF Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Froblem TP16B0SM SEG Fix machine stop when setting the Compact PDF option and changing color setting to Mono in Easy setting during scan. Problem TP16A0OQ SEA Correct the problem that certain SFE functions are turned off after HDD recovery. Requirement - KOREA Improve fax widget button size and space between buttons for user convenience. Problem - DEV Add HDD defect check function in HDD recovery mode screen. Problem - DEV Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle Problem - DEV Fix the device stop when setting double-sided, 400% enlarge option in copy job. Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a Car and TRC jobs are impropely Problem TP16BOCT SEAU Fixed the For arriage hitting the frame when scanning 432mm media on the platten. Problem TP16BOCT SEAU Fixed the Fixed period period page being intermittently missing when DCF/HCF paper is empty Fixed the Fixed the error repage not being printed abnormally in the solution environment's printing case. Problem TP16BOCT SEAA O00610 SECA O0 | II . | Problem | TP16A0B5 | SEA | Fix a problem where the machine reboots when using small paper that is not supported by DSDF. |
| Problem TP16B0LX SECA Fix an issue where JAC enable / disable do not work by job type via Fleet Admin Pro. | II . | | TP16B017 | SEG | Use a temporary file name while scaning and saving the file, and rename it after the saving is |
| Problem TP16B0LX SEPOL Fix a problem that causes the device to freeze when the scanned image is skewed from the Problem TP16B0ON SEI Fix a problem that cause performance degradation when using counter widget. Problem TP16B0SM SEF Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix machine stop when setting the Compact PDF option and changing color setting to Mono in Easy setting during scan. Problem TP16A0QQ SEA Correct the problem that certain SFE functions are turned off after HDD recovery. Requirement - DEV Add HDD defect check function in HDD recovery mode screen. Requirement - DEV Fix the problem that certain SFE functions are turned off after HDD recovery. Problem TP1670VH SEG Fix the problem where scan data transfer is slowed down for a sync problem when there are a lot Problem - DEV Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle Problem - DEV Fix the device stop when setting double-sided, 400% enlarge option in copy job. Problem TP1690W6 SEF Fixed several bouygues telecom issues. Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16A0NI SEBN Fixed the Fix carriage hitting the frame when scanning 432mm media on the platter. Problem TP16B0ZT SEAU Fixed the Fix carriage hitting the frame when scanning 432mm media on the platter. Problem TP16B0ZT SEAD Fixed the Fix carriage hitting the frame when scanning 432mm media on the platter. Problem TP16B0ZT SEAD Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP16B0ZT SEAD Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP163B0Z SEA SEA OV0-1507- SEG SEA OV0-1507- SEG SEA SEA OV0-1506- | (2017-01-23) | Problem | TP1680JS | | |
| Problem TP16B0ON SEI Fix a problem that cause performance degradation when using counter widget. Problem TP16B0SM SEF Fix an issue where the total sent page is incorrectly displayed in the fax sent report when Fix machine stop when setting the Compact PDF option and changing color setting to Mono in Easy setting during scan. Problem TP16A0OQ SEA Correct the problem that certain SFE functions are turned off after HDD recovery. Requirement - DEV Add HDD defect check function in HDD recovery mode screen. Requirement - KOREA Improve fax widget button size and space between buttons for user convenience. Problem TP1670VH SEG Fix the problem where scan data transfar is slowed down for a sync problem when there are a lot Problem - DEV Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle Problem - DEV Fix the device stop when setting double-sided, 400% enlarge option in copy job. Problem TP1690W6 SEF Fixed several bouygues telecom issues. Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16B0CT SEAU Fixed the Fixed the Fixed the frame when scanning 432mm media on the platten. Problem TP16B0CT SEAU Fixed the Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP16B0CT SEA SECA VO-1506- O00610 SECA VO-1507- O00139 Requirement Problem SEA SECA O00610 SECA VO-1507- O00139 Requirement DEV Developed a new spm for full build job support (The app will be released in the app center next Regualr FW Problem DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Applied a new CMS function for print image quality improvement. | | | | | |
| Problem TP1690PR SEG Fix an issue where the total sent page is incorrectly displayed in the fax sent report when TP1690PR SEG Fix machine stop when setting the Compact PDF option and changing color setting to Mono in Easy setting during scan. Problem TP16A0OQ SEA Correct the problem that certain SFE functions are turned off after HDD recovery. Requirement - DEV Add HDD defect check function in HDD recovery mode screen. Requirement - KOREA Improve fax widget button size and space between buttons for user convenience. Problem TP1670VH SEG Fix the problem where scan data transfer is slowed down for a sync problem when there are a lot Problem - DEV Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle Problem - DEV Fix the device stop when setting double-sided, 400% enlarge option in copy job. Problem TP1690W6 SEF Fixed several bouygues telecom issues. Problem TP1680CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16A0NJ SEBN Fixed the Fx carriage hitting the frame when scanning 432mm media on the platten. Problem TP166162 SEDA Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP168027 KOREA Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP168010 SECA VO-1507- SEG MO00610 SECA VO-1507- SEG MO00139 SECA VO-1507- SEG MO0 | | | | | |
| Problem TP1690PR SEG Fix machine stop when setting the Compact PDF option and changing color setting to Mono in Easy setting during scan. Problem TP16A0OQ SEA Correct the problem that certain SFE functions are turned off after HDD recovery. Requirement - DEV Add HDD defect check function in HDD recovery mode screen. Requirement - KOREA Improve fax widget button size and space between buttons for user convenience. Problem TP1670VH SEG Fix the problem where scan data transfer is slowed down for a sync problem when there are a lot Problem - DEV Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle Problem Q1611_0054 KOREA Fix the problem where the device is slowed down when ACR and TRC jobs are impropely Problem TP1680CT SEAU Fixed the verice when setting double-sided, 400% enlarge option in copy job. Problem TP1680CT SEAU Fixed several bouygues telecom issues. Problem TP16A0NI SEBN Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16A0NI SEBN Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. Fixed the From page not being printed abnormally in the solution environment's printing case. Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the TP1630R0 VO-1507- SEG MO0610 SECA VO-1508- SEGA | | | | | |
| Problem TP16A0OQ SEA Correct the problem that certain SFE functions are turned off after HDD recovery. Requirement - DEV Add HDD defect check function in HDD recovery mode screen. Requirement - KOREA Improve fax widget button size and space between buttons for user convenience. Problem TP1670VH SEG Fix the problem where scan data transfer is slowed down for a sync problem when there are a lot Problem - DEV Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle Problem - DEV Fix the device stop when setting double-sided, 400% enlarge option in copy job. Problem Q1611_0054 KOREA Fix the problem where the device is slowed down when ACR and TRC jobs are impropely Problem TP1690W6 SEF Fixed several bouygues telecom issues. Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16A0NJ SEBN Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. Problem TP166162 SEDA Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP1630R0 VO-1506- VO-1506- SEA VO-1507- SEG 000610 SECA VO-1507- SEG 000139 Requirement - DEV Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the Regualr FW release officially) Developed a new app for full build job support (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed ide jam count duplication on the error report in ADF jam cases. | | | | | Fix machine stop when setting the Compact PDF option and changing color setting to Mono in |
| Requirement - DEV Add HDD defect check function in HDD recovery mode screen. | | | | | , , , |
| Requirement KOREA Improve fax widget button size and space between buttons for user convenience. | | | TP16A0OQ | | · · · · · · · · · · · · · · · · · · · |
| Problem TP1670VH SEG Fix the problem where scan data transfer is slowed down for a sync problem when there are a lot Problem - DEV Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle Problem - DEV Fix the device stop when setting double-sided, 400% enlarge option in copy job. Problem Q1611_0054 KOREA Fix the problem where the device is slowed down when ACR and TRC jobs are impropely Problem TP1690W6 SEF Fixed several bouygues telecom issues. Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16A0NJ SEBN Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. Problem TP166162 SEDA Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP16B027 KOREA Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP1630R0 VO-1506- MO0610 SECA WO-1506- MO0610 SECA SECA WO-1507- MO0139 Requirement Problem - DEV Developed a new app for full build job support (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | | - | | · |
| Problem - DEV Fix a false alarm which misunderstands that IP conflict occures from ARP protocol cache handle Problem - DEV Fix the device stop when setting double-sided, 400% enlarge option in copy job. Problem Q1611_0054 KOREA Fix the problem where the device is slowed down when ACR and TRC jobs are impropely Problem TP1690W6 SEF Fixed several bouygues telecom issues. Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16A0NJ SEBN Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. Problem TP166162 SEDA Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP16B0CT KOREA Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP1630R0 VO-1506- SEA 000610 VO-1506- SEA VO-1507- SEG Developed a new app for full build job support (The app will be released in the app center next Regualr FW release officially) Requirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | • | - TP1670VH | | · · · · · · · · · · · · · · · · · · · |
| Problem - DEV Fix the device stop when setting double-sided, 400% enlarge option in copy job. Problem Q1611_0054 KOREA Fix the problem where the device is slowed down when ACR and TRC jobs are impropely Problem TP1690W6 SEF Fixed several bouygues telecom issues. Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16A0NJ SEBN Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. Problem - KOREA Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP166162 SEDA Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP1630R0 VO-1506- SEA 000610 SECA VO-1507- SEG 000139 Requirement - DEV Developed a new app for full build job support (The app will be released in the app center next Regualr FW release officially) Problem - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | | - | | • • • |
| Problem Q1611_0054 KOREA Fix the problem where the device is slowed down when ACR and TRC jobs are impropely Problem TP1690W6 SEF Fixed several bouygues telecom issues. Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16A0NJ SEBN Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. Problem - KOREA Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP166162 SEDA Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP16B027 KOREA Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the TP1630R0 VO-1506- O00610 SECA O00610 SECA VO-1507- O00139 Requirement - DEV Developed a new app for full build job support (The app will be released in the app center next Regualr FW release officially) Problem - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | | - | 1 | |
| Problem TP1690W6 SEF Fixed several bouygues telecom issues. Problem TP16B0CT SEAU Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized Problem TP16A0NJ SEBN Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. Problem - KOREA Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP166162 SEDA Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP16B027 KOREA Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the TP1630R0 VO-1506- SEA NO-1507- SEG O00610 SECA VO-1507- O00139 Requirement - DEV Developed a new app for full build job support (The app will be released in the app center next Regualr FW release officially) Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | | Q1611_0054 | | |
| Problem TP16A0NJ SEBN Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. Problem - KOREA Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP166162 SEDA Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP16B027 KOREA Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the TP1630R0 VO-1506- SEA O00610 SECA VO-1507- SEG O00139 Requirement - DEV Developed a new app for full build job support (The app will be released in the app center next Regualr FW release officially) Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | Problem | TP1690W6 | SEF | Fixed several bouygues telecom issues. |
| Problem - KOREA Fixed the error page not being printed abnormally in the solution environment's printing case. Problem TP166162 SEDA Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP168027 KOREA Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the TP1630R0 VO-1506- 000610 SECA VO-1507- 000139 Developed a new app for full build job support (The app will be released in the app center next Regualr FW release officially) Requirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | Problem | TP16B0CT | SEAU | Fixed the Searcheable PDF not being generated when a certain complex pattern is recognized |
| Problem TP166162 SEDA Fixed the issue of a printed page being intermittently missing when DCF/HCF paper is empty Problem TP16B027 KOREA Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the TP1630R0 VO-1506- 000610 SECA VO-1507- 000139 Developed a new app for full build job support (The app will be released in the app center next Regualr FW release officially) Requirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | Problem | TP16A0NJ | SEBN | Fixed the FR carriage hitting the frame when scanning 432mm media on the platten. |
| Problem TP16B027 KOREA Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the TP1630R0 VO-1506- O00610 SECA VO-1507- O00139 Pequirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW release officially) Requirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | Problem | - | KOREA | Fixed the error page not being printed abnormally in the solution environment's printing case. |
| Requirement TP1630R0 VO-1506- 000610 SECA VO-1507- 000139 Requirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | Problem | TP166162 | | |
| Requirement VO-1506- 000610 VO-1507- 000139 Requirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | Problem | | KOREA | Fixed the issue of quota not being reset at times when the device goes into the sleep mode at the |
| Requirement 000610 VO-1507- 000139 SECA VO-1507- 000139 Requirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | | | CE A | |
| VO-1507- 000139 Requirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | Requirement | | | |
| Requirement - DEV Developed a new Smart Scan app (The app will be released in the app center next Regualr FW Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | quii ciii ciii | VO-1507- | | Regualr FW release officially) |
| Problem - DEV Fixed the Schedule Image Overwrite automatically changing from on to off when powering the Requirement - DEV Applied a new CMS function for print image quality improvement. Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | Requirement | - | DEV | Developed a new Smart Scan app (The app will be released in the app center next Regualr FW |
| Problem - DEV Fixed idle jam count duplication on the error report in ADF jam cases. | | | | | |
| | | Requirement | - | DEV | Applied a new CMS function for print image quality improvement. |
| Problem - DEV Improved screen transition speed between tabs on UI OOB app. | | Problem | - | DEV | Fixed idle jam count duplication on the error report in ADF jam cases. |
| | | Problem | - | DEV | Improved screen transition speed between tabs on UI OOB app. |

| 11 | n . | mp | lan. | M PC 1d IDAD |
|--------------|----------------------------|--|-----------------------|--|
| | Requirement | TP164027 | SEA | Modified the LDAP contact usernames to display either surname or given name. |
| | Requirement | TP1640FF | SEA | Added a default contact selection feature between LDAP and local contacts in the Send app. |
| | Requirement | TP1650OK | SEA | Added SSO support to allow LDAP search using Kerberos ID/PW. |
| | Requirement | - TD1 65011 | KOREA | Added ITB band generation adjustment feature in the service mode to prevent blade damages |
| V6.D6.29.03. | Requirement | TP165011 | SEG | Added the Borderless printing feature. (SFE56) |
| 120609 | Requirement | TP1660JA | SEA | Added buckle adjustment feature in the service mode. |
| (2016-12-08) | Problem | TP16611L | SEUK | Fixed the intermittently changing home screen setting issue with wifi enabled. |
| | Problem | TP16610X | SEBN | Fixed the issue of Tray5 info not showing on the supply report. |
| | Requirement | - | SEF | Added a new feature for the x-ray print mode for x-ray image improvement. |
| | Problem | TP1670O8 | SEA | Fixed the VNC connection issue when using a password with a certain character. |
| | Problem | TP168030 | SEA | Fixed the intermittent booting issue after a FW update fail. |
| | Problem | TP1680K1 | SEIL | Fixed the issue of VNC setting menu not showing correctly in Hebrew. |
| | Problem | TP1670IC | KOREA | Fixed remaining roller counts showing as negative numbers in the Counthru environment. |
| | Problem | TP168100 | SENA | Fixed Swedish punch not working in a print job. |
| | Problem | - | KOREA | Fixed imaging unit or toner cartridge being recognized as uninstalled at times. |
| | Requirement | - | DEV | Added a P-Knox security package function. |
| | Problem | TP1680P0 | SEA | Fixed job stopping at times when printing using a driver with a 3-hole punch option selected. |
| | Problem | TP169064 | SENA | Fixed the printing error when using remote pull printing in the Printing Security Core solution. |
| | Problem | TP1680JH TP1670W4 | SEAU | Fixed fax reception stopping with an invalid caller ID coming through. |
| | Problem | TP1680V3 | SENA | Fixed intermittent jams when printing on Extra heavy weight2 media in duplex. |
| | Requirement | TP1690AQ | SECA | Added Letter/Legal MSO fax reception functionality. |
| | Problem | TP1690MM | SENA | When selecting fixed the menu display revert Swedish or Hungarian language, the device storage |
| | Problem | TP1640A0 | SEAU | When entering D or d after connecting external keyboard to USB, input value is not displayed |
| | Problem | TP16A020 | SEUK | When pushing start button before From/To values of send app are prefilled, send job is not |
| | Problem | TP16A0FH | KOREA | SFE feature setting value changes to default from time to time. |
| | Di | SR-1508- 000118 | CE A | The total year accounts increased from 500 to 2000 |
| | Requirement | VO-1508- 000350 | SEA | The total user accounts increased from 500 to 2000. |
| | Fixed issue | TS-1512- 000029 | SEAU | Intermittent job pending issue during scanning a large volume of media with compact PDF as an option was resolved. |
| | Fixed issue | TP1640UT | SEAU | Removed the improper ACR cleaning animation in MX7. |
| | Requirement | TP1640K5 | SEG | Printing on a number of paper types including Letterhead / Punched / Preprinted was improved. |
| | Fixed issue | TP16500E | KOREA | Corrected job pending issue during duplex V folding in MAC OS. |
| | Fixed issue | TP1660HG | SEG | Modified mistranslation in German. |
| | Fixed issue | TP1650R8 | SEUK | Resolved the issue of which the print job is always printed on A3 regardless of what user selected |
| | Fixed issue | TP1660GU | SEA | Intermittent print job stoppage when user processes complete after DSDF jam. |
| | Fixed issue | TP1660NE TP1650IT | SESA | Resolved the issue of which reduced information, which was saved when program is generated, |
| | Requirement | TP1650FP | KOREA KOREA | Added a feature that can allow FAP monitoring of inactivation function of USB memory stick. Added an option that enables changing the priority order of multi-use paper tray during copy, |
| V6.D6.29.02. | Requirement Fixed issue | TP1660VG | SEA | S5-3111 error not being displayed in error report was fixed. |
| 102513 | Fixed issue | TP166162 | SEDA | Fixed the issue of which the printer continues to print from a printable tray rather coming to a |
| (2016-10-31) | Fixed issue | TP16703Z | SEA | Took out the description about features that are not applied to Help app. |
| | Fixed issue | TP167054 | KOREA | Resolved the issue of system user being logged on instead of an actual print user when the user |
| | Fixed issue | TP16701V | SEA | Fixed the issue of +Me Box still running even when Box Application is disabled. |
| | Requirement | TP1630TE | SEF | Added an option to maintain Jam animation until error is cleared. |
| | Fixed issue | TP167097 | SEBN | Secured a compatibility of PDF/A Scan file with ISO 19005-1. |
| | Requirement | TP1670DA | KOREA | Added a feature to allow use or delete scan/ transmission destination. |
| | Requirement | TP1670PP | KOREA | Added a function that aggregates usage data within a certain period of time selected by Counter |
| | Fixed issue Fixed issue | TP16601Y TP16502A | SEUK KOREA | Fixed user being automatically logged out while using MagStipe Readers login. Improved the issue of the system slowing down in DHCP mode without DHCP server |
| | Fixed issue | TP1670CF | SECA | connection. Correcting intermittent 1st and 2nd printing image mixed issue in case of Mono printing. |
| | Fixed issue | TP1680J3 | SECA | Fixed MP tray setting value is changed after Power on/off in case of envelop size. |
| | Fixed issue | TP16706H | SECH | Fixed slow printing issue when the set enables JAC Fleet Admin. |
| | Fixed issue | TP1680F1 | KOREA | Fixed imaging unit failure problem when OPC or Deve Unit has H/W damage. |
| | Requirement | VO-1509- 000191 SR-1507- 000561 | SEG SEF | Adding a feature to align the secure job list in LIFO and FIFO forms as preferred by user. |
| | Requirement | TP1650L8 | SEDA- SIMPRES S | Adding a feature to turn on/off alarm for toner status when it's low. |
| | Requirement | SR-1507- 000568 | SEG | Adding a selecting feature for a paper tray and a media type using a PJL command. |

| п | | | | |
|----------------------------|----------------------------|----------------------|--------------|--|
| | Requirement | SR-1507- | SEG | Adding a feature of sending state information only when the entire job is completed for any job |
| | | 000568 SR-1506- | | linked to VPSX server. |
| | | 000840 | SEBJ | |
| | Requirement | VO-1410- | SEA | Adding a PC scanning feature using a USB cable. |
| | | 000185 | Korea | |
| | Requirement | TS-1508- 000397 | SEDA | Supporting UBS flash drive in NTFS format. |
| | | SR-1509- | | Adding a feature for making a document box invisible to users who login as SWS when admin |
| | Requirement | 000477 | Korea | disables the box. |
| | | VO-1511- | | |
| | | 000153 | | |
| | | SR-1601- | SECA | |
| | Requirement | 000115 | Korea | Adding a feature to allow users reboot a set at their desired time/cycle. |
| | | VO-1511- 000059 | SEI | |
| | | TP1660B4 | | |
| | | TP16610P | | |
| | | TS-1511- | | |
| | | 000581 | | |
| | Fixed issue | TS-1511- | SEF | Improving the issue with intermittent failures when setting options for copy and/or authorization |
| | | 000582 | | as Fleet Admin. |
| | | TS-1511- 000583 | | |
| | | VO-1508- | | |
| | Requirement | 000490 | Korea | Disabling warning messages when the cover is open during platen scan. |
| | Requirement | VO-1509- 000398 | SEUK | Adding a delete and a preview feature during box printing. |
| | | | | M. N.C. Letter and D. D. M. H. L. |
| | Requirement | SR-1510- 000416 | SELV | Modified to print a box-saved PRN file with Drive options that were applied when generating the PRN. |
| | | VO-1511- | app | Adding a feature to display telephone numbers or names (as saved in the address book) in the Fax |
| | Requirement | 000388 | SEF | Sent Report. |
| | | VO-1411- | | |
| | | 000459 | SENA | Ally The law in the Theory is a control to |
| | Requirement | VO-1511- | SEF | Adding a Test button in the E-mail notification setting for an SMTP check. |
| | | 000431 | | |
| | | SR-1512- | | |
| | Requirement | 000207 | SAPL | Adding a feature to reset a user's personal accounting information. |
| V6.D6.29.01. | Fixed issue | TP1640HA | SEAU | Corrected the problem of a job being cancelled when Print job control is OFF and FDI balance is |
| 081720 (2016-08-19) | | | SEF | 0. |
| (2010-08-19) | Fixed issue | SR-1512- | SENA | Improving authentication errors when an FTP password contains ":". |
| | | 000319 | | 1 |
| | Fixed issue | TS-1601- | SEBN | Correcting the problem of test pattern not being printed in a service mode. |
| | T Inted 185de | 000638 | JEDI' | 5 1 5 |
| | Fixed issue | Q1603_0175 | Korea | Improving the connection failure problem due to non-support for NOOP command in a certain |
| | | | | SMTP server. |
| | Fixed issue | TP1630CO | SEBN | Adding additional paper types in the selection during Google cloud printing. |
| | Fixed issue | TP1630PW | Korea | Correcting intermittent failures of Color mode printing or color document being printed in mono |
| | | | | during auto copying. |
| | Fixed issue | Q1603_0263 | Korea | Correcting intermittent Power off malfunctions in NFC user interface. |
| | Fixed issue | TP1640AE | SEAU | Improving intermittent Kerberos authentication errors due to timing issue after powering on/off. |
| | Fixed issue | TP1640EO | SEBN | Improving poor Dutch translation. |
| | Fixed issue | TP1640F8 | SEAU | Improving the issue of Multi destination emails not being sent when using a certain SMTP server. |
| | | SR-1503- | 1 | |
| | Requirement | 000854 | SEA | Adding a feature to recognize papers smaller than A4.Letter as A4.Letter during scanning. |
| | Requirement | SR-1509- | Korea | Adding a feature to include PSTN line state information in Fax Diagnostic Report. |
| | - | 000006 | | |
| | Requirement | TP1650U601 | Korea | Supporting special characters (<, >, ") for a password. (If usage environments is solution, then need to B2B driver and solution) |
| | Fixed issue | TD1630CV | Kores | Improving reading errors when using EPSoft card readers. |
| | Fixed issue Fixed issue | TP1630CY TP16500S | Korea SEA | Improving print errors due to wrongly generated data during LPD/LPR print data processing. |
| | Fixed issue | N/A | DEV | Improving the issue of U3-3313 jams caused by intermittent paper slips. |
| | Requirement | TP1650NU | SEAU | Adding a feature to require a PIN for a color print when selecting a color PIN mode. |
| | Fixed issue | TP1640IT | SSA | Improving the issue of completed secure print job remaining on the job list. |
| Ш | | | | i i i i i i i i i i i i i i i i i i i |

| II | | 1 | | |
|-------------------------|-------------|----------------------------------|-------------|---|
| | Fixed issue | TP1630AU | SEA | When previewing PDF or TIFF images on Box App, the previewed image may have unexpected white blank on right side if it was scanned with mono mode |
| | Fixed issue | TP1630FS TP1661SE | SEA SECA | During Scaning with compact PDF option, Set locks up at times. |
| | Fixed issue | TP16403C | SEAU | Fixing memory leackage issue according to repeated solution install/uninstall. |
| | Fixed issue | TP1640IZ | SEG | The poor German translation(StauWdrherste) will be changed. |
| | Requirement | SR-1508- 000346 | SESA | Adding specific setting method through PJL command PCL font size, Tray1 paper size, Mp Tray paper size. |
| | Fixed issue | TS-1603- 000018 | SEUK | Correcting the problem of complex PDF document not being printed intermittently. |
| | Requirement | TP1660DJ02 SR-1507- 000265 | SEG SEAU | Adding Numeric keypad for PIN code input in solution (API only). |
| | Requirement | | SEUK | Adding APK installation method in the Fleet Admin Pro. |
| | Fixed issue | TP16613F | SEA | Fixing wrong IP address displaying on the notification screen in case of DHCP mode. |
| | Fixed issue | TP16502T | SEA | Fixing powerpoint abnormal output from MAC office 2016. |
| | Fixed issue | TP1640KG | SEG | Improving performance of 1-bit indexed color image document. |
| | Fixed issue | TP16706H | SECH | Fixing printing job pending issue according to authentication fail. |
| | Fixed issue | TP1650AD | Korea | Improving scanning speed when user sends many fax images. |
| | Tixed issue | Q1601_0282 | Korca | Defective image quality due to toner overfeed when printing large number of low coverage |
| | Fixed issue | Q1501_0282 Q1511_0437 | KOREA | images (Augermark). |
| V6.D6.29 | Fixed issue | TP16500R | SEG | Fix inability to use '\$' character in Scan to SMB path. |
| (15-July- | Fixed issue | Q1604_0213 | KOREA | Fix occasional false alarms on HDD error (S1-2448, S1-2443) during FW upgrade. |
| 2016) | Fixed issue | TP1650DL | SEA | Fix printing is not restarted after removing BinFull (H2-8A33) error from booklet finisher. |
| | Fixed issue | TP165051 | SME | Fix occasional inoperability on Copy Widget + buttons. |
| | Fixed issue | TP1660OX | KOREA | Fix printing jobs are held at times when burst job request is received. |
| | Fixed issue | TP1640DH | SEUK | Enhanced overall UI performance for a case where a device supports more than 501 external user IDs. |
| | Fixed issue | TS-1601- 000563 | SESG | Fixed a job pending issue during Scan to SMB using NetApp SMB server. |
| | Fixed issue | TP16303L03 | SESG | Fixed an issue of user email not being prefilled in Send App during the Basic and Application Auth Mode while using Safecom solution. |
| | Fixed issue | TP16303L03 | SESG | Fixed an issue of Safecom pull print application closing immediately after a user login. Enhanced the safecom login operations for time-dependent cases. |
| | Fixed issue | TS-1601- 000202 | SENA | Enhanced user login performace (reduced the login time) for a case where hundreds of secure print jobs are stored in a device. |
| | Fixed issue | TP1630D701 | SEI | Applied a scan authority checking process for a case where Dynamic Workflow is executed in the Application Auth mode before Send Applaunches after the device boots up. |
| | Fixed issue | TP1630JX | SEI | Enhanced the performance of overall email notification service features. |
| | Fixed issue | TP1640XN | SEI | Enhanced copy widget performance for a case where a user tries to conduct a job immediately after a device boots up or wakes up from a power save mode. |
| | Fixed issue | TP16500J01 | SEG | Fixed to handle invalid command sets in a print data (PRN) file received from AS400 server. |
| | Fixed issue | TP1630TE | SEF | Disabled the PDF/A option for 600 dpi resolution in Send app. |
| | Fixed issue | TP1630TE | SEF | Added finisher errors (H2-6531,H2-6533) to error history reports. |
| | Fixed issue | TP1630HK | SEBN | Fixed an issue of not cloning the authentication status in the admin setting for printing. |
| | Fixed issue | TP1630RK | SEBN | Improved the toner gauge accuracy for eco printing where toner usage is very low. |
| | Fixed issue | TP1640M0 | SEBN | Fixed an issue of applying incorrect tray protection settings to the UI. |
| | Fixed issue | TS-1601- 000468 | SEAU | Fixed an issue of scan images having a light background when a scan job is done with an "Auto Color: Color/Mono" option on. |
| | Fixed issue | TP1630CM | SEA | Fixed an issue of device card login not working sometimes in a sleep mode. |
| | Fixed issue | TS-1602- 000038 | SEA | Enhanced print performance for duplex images (color/mono mixed images). |
| V6.D6.27.EC | Fixed issue | SR-1602- 000557 | SEA | Enhanced copy print output performance for a copy job with 1 to 2 Duplex using 7 original documents. |
| 1603.05 (03-Jun- | Fixed issue | TS-1603- 000002 | SEA | Added more animations for paper jam clearing guidance. |
| 2016) | Fixed issue | TS-1511- 000148 | SEA | Made Scan to FTP compatible with Serv-U FTP server. |
| | Fixed issue | TP1640GR | SEA | Fixed an issue of output images becoming brighter for mixed-size original (MSO) copy in a simplex mode. |
| | Fixed issue | TP164030 SR-1510- 000459 | SEA | Improved the balnk page detection rate especially for jobs with a Mono or Grey mode. |

| II | | 1 | 1 | |
|-------------------|-------------|----------------------|--|---|
| | Fixed issue | TP1650TS | SEA | Added SFE055 to enable users to select the sensor-detected #10 envelope paper size on a tray confirmation popup. |
| | Fixed issue | TS-1601- 000459 | SAPL | Fixed an issue of color options not being able to be saved as default in Quick Copy in a Device Authentication mode. |
| | Fixed issue | TP16400T04 | KOR | Fixed the login page sometimes displaying a white screen. |
| | Fixed issue | TP1630RG | KOR | Enhanced Copy widget printout performance to be as powerful as that of Copy App. |
| | Fixed issue | TP1640H0 | KOR | Enhanced secure job cancel function to delete received data completely. |
| | Fixed issue | TP165022 | KOR | Fixed Autologout not working sometimes in the Device UI. |
| | Fixed issue | - | - | MyPage App is restricted for external authenticated users as per the spec. |
| | Fixed issue | - | - | Fixed an issue of a machine continuously warming up due to C8-3314 (Toner Supply Error) when powered on. |
| | Requirement | - | _ | Applied security compliance requirements from the Korean Government. |
| | Fixed issue | - | - | Fixed a finisher error (H2-8262) which occured when executing a C-fold simplex print job right after a V-fold simplex print job. |
| | Fixed issue | - | - | Fixed a 4K-Finisher jam error which occured when an OHP flim is used for copy. |
| | Fixed issue | _ | - | Fixed book erase not working in Copy App when the Custom option is selected as korean. |
| | Fixed issue | - | - | Changed the version check policy to allow update for an engine sub firmware when the second sequence of its version name is different from the current one. |
| | Fixed issue | _ | | Improved the management of the IP filtering feature and its default values. |
| | Fixed issue | _ | | Fixed a rarely-occuring device lockup issue in powersave. |
| — | Fixed issue | N/A | KOREA | Print jobs are held at times when SecuThru (a secure printing software) is used. |
| | Fixed issue | TP1630B8 | SEA | The fuser cleaning sheet is not printed when the default paper size is Letter. |
| | | TS-1602- | | 1 1 |
| | Fixed issue | 000104 | SEAU | GCP service fails as an expired key is not refreshed. |
| | Fixed issue | N/A | SEAU | The fax redials the number that was previously entered when dialing using the fax keypad under |
| | Fixed issue | N/A | SEAU | Send Job Cancel does not work at times right after starting Send Job when the Searcheable PDF |
| | Requirement | N/A TS-1602- | SEA | New US standard setting values were applied. (Default values for US models) When making a searcheable PDF with a 300 dpi or lower resolution, scanned images are cropped |
| | Fixed issue | 000076 | SEG | and the text on the scans is hard to read in MS Word. |
| | Fixed issue | TS-1601- 000454 | SEAU | The device locks up intermittently during scan when Job Progress Window is off. |
| | Fixed issue | TS-1601- 000564 | SEUK SEG | Send does not work at times when Skip Blank Page is on. |
| V6.D6.27 | Fixed issue | SR-1602- 000397 | SEA | Scan to SMB fails if filename contains a space. |
| (25-Mar- 2016) | Fixed issue | TS-1512- 000456 | SEBN | The number of copies cannot be selected when IPP printing in MAC OS. |
| | Fixed issue | N/A | KOREA | Scan to PC shortcuts generated in a previous version (Vx.C6.xx) do not work after upgrading to |
| | Fixed issue | SR-1601- | SEI | Fax confirmation reports are not printed to fit one page. |
| | | 000384 | SEG | |
| | Fixed issue | TP16307B SR-1601- | SEA | If the top bin of an inner finnisher is selected as the output tray, UI progress information is |
| | Fixed issue | 000624 | SEA | If Home Lock is enabled for all users, duplicate icons appear on the Home screen at times. |
| | Fixed issue | SR-1601- 000624 | SEA | If a user changes the setting of Copy Customizer, the copy OOB setting also changes. |
| | Fixed issue | TS-1602- 000036 | SEA | The Compact PDF option does not work when scanning with the Auto Color Mode on. |
| | Fixed issue | TS-1602- 000036 | SEA | Scan Adjustment was modified to work according to the default paper size (A4 or Letter) of a country/region in which the machine will be used. |
| | Eine 1. | TS-1601- | CE A | An output tray selected for incoming faxes changes back to the default tray after waking up in a |
| | Fixed issue | 000186 | SEA | power save mode. |
| | | Add Func | | Support function to create "Web page" shortcuts on the main UI. |
| | | Add Func | | Support Scan ACS Function : In send app, "Auto" Mode (Automatic Color selection) is added. |
| | | Add Func | | V folding support for print jobs. |
| | | Add Func | | Added PIN only authentication mode. |
| | | Add Func | | Error code and description improved. Provides detailed information. |
| | | Add Func | | SSL, TLS, None are supported for SMTP from SWS |
| V6.D6.08 | | Fix defect | | The paper option is displayed Custom size on Apple device. |
| (18-Jan- | | Fix defect | | B4 paper size can not be recognized properly. When two interfece (February Wife) have some ID Address. ID conflict amort message will be |
| 2016) | | Fix defect | | When two interface (Ethernet/Wifi) have same IP Address. IP conflict error message will be displayed on UI board. |
| | | Fix defect | | If Application Authentication is enabled, previouly created short-cut does not work. |
| | | Fix defect | | Not able to send fax for more than 15 recipients. |
| | | Fix defect | | The output has wrong page order of booklet. |
| | | Fix defect | | You may see that LCD is black after wakeup by touch or wakeup by jobs. |
| 1 | | Fix defect | | File can not be deleted from Box. |
| | | | | |

| | Fix defect | Booklet printing speed is improved. |
|------------------------------|-----------------------|--|
| | Fix defect | User is not able to edit Wi-Fi IP settings. IP Setting menu from UI is disabled intermittently. |
| V6.A6.28 (8-Oct-2015) | Fix defect | TC control parameter change for improvement of toner scattering according to the developer life. |
| | Fix defect | Correct sensor deviation by CTD Sensor Calibration algorithm. |
| V6.A6.25 (07-Sep-2015) | Fix defect | Fix defect of 2K Booklet Finisher jam. |
| | Fix defect | Fix defect that Original size detection is failed in case of ADF open in Copy job. |
| | Fix defect | Copy Save to box -> Store and print file name overwrite issue. |
| | Fix defect | Fix defect that Scan to USB job is not happening after OHD Job. |
| | Fix defect | Improve, SWS set 400%, Copy show 400 %. but output paper is 100% issue. |
| | Fix defect | Fix that App crash is observed if user taps on to the UI while image loading is on progress. |
| | Fix defect | Fix not for launching Send App. |
| | Fix defect | Fix defect that the overwrite function doesn't work when import address book CSV file under GUI. |
| | Fix defect | PaperCut flicking issue. |
| | Fix defect | Changing of OPC life calculation logic. |
| | Fix defect | Fix Jam issue which has been occurring from MP tray. |
| | Fix defect | Fix duplex printing skew. |
| | Fix defect | Improve detecting Document. size feature. |
| | Fix defect | Fix defect that, after Initial setup, rebooting is not processed properly. |
| | Fix defect Fix defect | Fix defect when duplex print, broken image can be printed out in 2-2 Copy. Fix back side 5mm band contamination issue. |
| | Fix defect | Support Korean language file name on ScanToPC menu. |
| | Fix defect | Supply security patch for Apk integrity. |
| | Fix defect | Machine rebooted very very rarely at receiving in case Machine is turned on by soft power on. |
| | Fix defect | Fix defect that user can't cancel current job sometimes. |
| | Fix defect | Fix defect of S5-3111 error during power save procedure. |
| | Fix defect | Fix defect of showing S5-3111 error on UI after sending print job while machine stays in sleep mode. |
| | Fix defect | Fix defect that machine will not wake up from UI sleep mode in spite of wake up event. |
| | Fix defect | Fix wrong translation in Finnish. |
| | Fix defect | Fix Scan & send App to launch properly. |
| | Fix defect | Fix defect of not deleting job list in UI. |
| | Fix defect | Fix defect that there is no action when press tray lock icon on notification bar. |
| | Fix defect | Fix defect that XOA-Web login page issue. (showing home page instead of Xoa application page). |
| | Fix defect | Improvement, unsupported input char are allowed in Send app. |
| | Fix defect | Fix defect of not working copy widget. |
| | Fix defect | Add function to Send App of removing destinations after the Job is started. |
| | Fix defect | Fix defect that the Send App was crashed while launching the program with Auto start option, sometimes. |
| | Fix defect | OPC Remain Algorism modification. |
| | Fix defect | Improve the fuser heating period on ready status. |
| | Fix defect | Improve Inner Finisher feature. |
| | Fix defect | Fix defect of 3K Finisher error. |
| | Fix defect | Fix defect of changing tray Job being occurred abnormally. |
| | Fix defect | Fix defect that the AA method is reset to 'Local' after the admin. enables/disables SFE13. |
| | Fix defect | Fix that Skip blank page option is not working in send. |
| | Fix defect | Fix defect of rebooting by internal buffer overrunning. |
| | Fix defect | Fix defect of rebooting and broken image on 2-2 copy. |
| | Fix defect | Job status addition in Quick Launch. |
| | T III delect | Fix defect that when user adds manual route entry in routing table through SWS after reboot, |
| | Fix defect | user defined entry is lost and user is not able to set Wifi as default gateway. Add function of increased Font Size to 26 DP in Send application. |
| | Fix defect Fix defect | Improve printing of envelope. |
| | Fix defect | Fix defect that printer doesn't wake up from power save by usb printing. |
| | Fix defect | Fix defect of broken image on duplex print (A5 SEF 2 - 2 book copy To MP Tray with Finisher |
| | Fix defect | Changing toner CTS table. |
| | Fix defect | Fix file name issue of Korean character in ScanToPC. |
| | Fix defect | Fix not printing issue during Auto color balance. |