



HP Access Control (HPAC)
v15.1.5 Patch
Release Notes

1 Summary

This patch applies to HP Access Control version 15.1.0.

After updating Futuresmart SFPs with a 4.3" Mini-VGA display and Futuresmart MFPs with Futuresmart 3.7 and newer firmware revisions, the HP AC Pull Print icon no longer appears on the display. HP AC functionality on the device otherwise appears.

The following HP device models are affected when Futuresmart 3.7 or newer firmware are applied:

- Futuresmart SFPs with 4.3" UI:
 - M604/605/606
 - M506
 - X555
 - M651
 - M806
- Futuresmart MFPs:
 - M527
 - M630
 - M880
 - M525
 - CM4540

2 Installation instructions

To install the 15.1.5 patch, do the following:

1. Close the HP AC Admin Console if it is open.
2. Apply the HPAC 15.1.5 patch by running the setup.exe on a HPAC 15.1.0 server.

NOTE: The 15.1.5 patch can also co-exist with other 15.1.x patches.

3. Once completed, open the HP AC Admin Console and navigate to the Server Information Tile to confirm this patch update.
4. Verify functionality by confirming the HP AC Pull Print icon now shows on the device display as expected.