

Firmware Release Note



Model: SCX-8230, 8240 Series	Date: 08-Feb-2017
-------------------------------------	--------------------------

Version	Category	Change Description
V5.E6.03.EC150 9.07 (08-Feb-2017)	Fix Defect	An issue of ScantoEmail pending is fixed .
		When user tries to print job with copies option on Mac, it just printout 1 copy.
		Customer's complicated PDF file was not printed thru PCL6 driver with A3 paper size option.
		Blank page printed from Google cloud print service.
V5.E6.07 (15-Dec-2015)	Fix Defect	SNTP/DST - Timezone issue for Chile, Ukraine and USA Eastern Time
		Machine reboot continously with 1 hour period, after DST(Daylight Saving Time) clock shift happen.
V5.D6.07 (16-Feb-2015)		<ol style="list-style-type: none"> 1. After HDD changing, some count of Usage Report is incorrect. 2. Even though authentication is enable color copy, user can not use ScantoPC. 3. When printing a document having odd number of pages from tray3 or tray4, the last page takes more long time. 4. Note: Below problem occurs if only IP Assgined mode is DHCP & hibernation ON during Hibernation ON case, <ul style="list-style-type: none"> - Now MFP gets new IP address when we connect to different VLAN from DHCP server. If device is connected in different VLAN and Hibernation mode is enabled, IP address is not renewed with DHCP server. 5. Response timeout for LPD/LPR command during printing by LPR/LPD job. 6. IPP module is changed from C to java in order to resolve printing issue with IPP. 7. IP address was not renewed with DHCP server if device is creating Hibernation Image. 8. when the database file was broken, database was not recovered. 9. DSN Service writes a lot of logs. So the log should be modified. 10. When user make an export of the user list, the passwork is visible in plain txt. (security issue).

Fix Defect	<p>11. Dotted lines in a table are disappeared in color mode printing with Excel office 2011 and Mac OS 10.9.x, but it's Ok in B&W mode.</p> <p>12. After FW update is finished, UI shows the MSOK system error message.</p> <p>13. When user scan ""ScanToLocal"" using,</p> <ul style="list-style-type: none"> - DCW Api - ADF Scan (multi page scan) - File format: JPG <p>user can get only last page. (The other pages are not saved in local.)</p> <p>14. When SNMP GetBulkRequest comes in at least 100 times per a sec, SNMP would not respond.</p> <p>15. Printing may be slow when printing mass PDF.</p> <p>16. Scan to PC login failure after machine restarts is fixed.</p> <p>17. TR Control value is initialized after wake-up from power save.</p> <p>18. Disable Fax receive forward in SWS fax settings menu when solution applications is installed.</p> <p>19. User authentication is not working for Scan TO PC when user changes password from SWS.</p> <p>20. Firefox browser user when upload long filename, filename inconvenience fixed.</p>
	<p>21. Fix AS400 Printing issue. Problem : not printing the file.</p> <p>22. In Hibernation mode, old scan to pc values were reflecting during boot up. Hence issue was arising at EPM side.</p> <p>23. Fax History report was not printed automatically after 50 Fax job.</p> <p>24. Error message displays in GUI sometimes.</p> <p>25. GUI operation goes slower and slower while using GUI without POPO.</p> <p>26. If the user is canceling a fax job, the next job is received was not the work. Fixed so that the next incoming job is completed successfully.</p> <p>27. When user go to Fax OOB basic page then UI crash was happening sometimes.</p> <p>28. In finnish language, the error message has been corrected from "Replace Cyan Drum unit end of life to Replace Black Drum unit end of life."</p> <p>29. In SWS > Settings > Machine Settings > General Setup, AutoCR option is added to set LF, LF+CR.</p> <p>30. CIFS enablement setting value is changed to default after FW upgrade.</p>
	<p>31. On Card Login after machine reboot, User is not able to access the AppList after clicking on host name in ScanToPC.</p> <p>32. Select paper size A6 in MP-Tray showing wrong value for its dimensions (x: 149, y: 105). Rectified A6 dimension value(x: 148, y: 105).</p> <p>33. Does not work without the passcode from the fax polling.</p> <p>34. Network Setting Menu 'Network Test' is overlapping with the 'Wi-Fi'.</p> <p>35. The login window is not shown over 10 min after POPO if BCPS 1.2 Solutions are installed.</p> <p>36. Duplex and simplex job jam issue using job seperator.</p>
Add Func.	<p>1. Support BCPS applications on XOA-Web version</p> <p>2. Support SFE007</p> <p>3. Bar code and QR code are added in configuration report.</p>

	Change Spec.	<ol style="list-style-type: none"> 1. Improvement - Supplement copy image cutoff in case of copying 2. Custom size longer than a standard paper size. 3. SPDS(Smart Printer Diagnostic System) is updated <ul style="list-style-type: none"> - WiFi-direct connection is supported - Shading test is supported - Fax Report is supported - Cloning is supported - Upload log is supported 4. Improvement process time of scan to PC job 5. TTI font is changed from vector to bitmap. 6. Improved for card tagging login and print job delay. 7. Improved Add printer via Web Service on Device. 8. Apply changed timezone of Russia. 9. When printing with Tray 3 when finisher is installed, machine is slow.
V5.C6.40 (05-Dec-2014)	Fix Defect	<ol style="list-style-type: none"> 1. Powersave Timeout option does not be applied. 2. Printing is slow when BCPS is used. 3. After Firmware upgrade is completed, normal boot progress is not worked. 4. Firmware upgrade is not progress at LUI (with USB stick). 5. When execute Memory Clear, time zone is not selected automatically. 6. Copy UI memory leakage improvement. 7. UI warning(Java Script Error) Pop Up. 8. After successful authentication, LUI doesn't move to home portal. 9. Toner Remains go back to 100% intermittently. 10. DADF 300dpi Scan Image Motion / Color Fringe Problem. 11. UI Memory Leak ScanToEmail/Job Status/ScanToServer/ Doc Box.
	Add Func.	<ol style="list-style-type: none"> 1. Compatible with main boards of 1GB and 2GB memory.
V5.C6.31 (30-Sep-2014)	Fix Defect	<ol style="list-style-type: none"> 1. Network-The printer cannot connect to AP as network key supports only 26 bits. 2. Screen switching from card animation to home window after swiping one of users' cards is very slow and sometimes machine seems to be stopped. 3. Error window is popped up when trying to print fax in secure receive mode in SWS. 4. The Paper mismatch screen pops up repeatedly after do PC print job with paper size 11x8 inch. 5. Cannot open Security Job UI with correct ID and Passcode from LUI. 6. The device cannot logout automatic after wake up from power save. 7. The Job history list cannot be seen on device when executing Scan to Home Folder After setting LDAP Attribut. 8. The custom workform icon is overflowed on Evergreen. 9. Scan To Cloud value did not reflect to Send To Others on Usage Counter Report. 10. Not able to set device power off by keeping pressing softkey. 11. Not wakeup after sleep mode through Inepro card reader. 12. Not reset autologout timer after sleep mode. 13. Cosmos-R HDD full issue. 14. NO Email Notification is received after performing Fax Send job. 15. The Count of Send doesn't increase after executing EDC Scan job. 16. The machine is hanging on Counter screen after executing User Usage Clear. 17. During printing report, device enter powersave mode. 18. Pop-up window "The UI is not being displayed correctly.." when select hardkey to change copies. 19. Send Error occurs and PC Fax job cannot be sent with Samsung Easy Security Manager.

Add Func.	1. HID Global R54270001-Con model supported. 2. Support DST(Daylight Saving Time).
-----------	---

※ Note

- Please do not turn off the printer and your computer until firmware update finishes.
 - If you are using USB connection, disconnect all other USB printers from the PC.
 - The firmware update you are about to install has been tested for compatibility with Samsung toner cartridge products ONLY.
- Installing The upgrade may cause a non-Samsung toner cartridge to malfunction.
- Do not run your printer during the firmware update.(Do not have any print job)