

Firmware Release Note

Model : SL-M2021/XIL, M2021/XIP

Date :

October 2, 2018

Version	Category	Change Description
V3.07.01.05 (14-Nov, 2014)	Fix Defect	The machine does not initialized.
V3.07.01.11 (22-Apr, 2016)	Fix Defect	Fix IP changing problem in DHCP mode
V3.07.01.12 (13-May, 2016)	Fix Defect	Enhance JAM problem
V3.07.01.24 (2-Oct, 2018)	Fix Defect	Fix the print quality(dim and dirty printing) issues

※ Note

- Please do not turn off the printer and your computer until firmware update finishes.
 - If you are using USB connection, disconnect all other USB printers from the PC.
 - The firmware update you are about to install has been tested for compatibility with Samsung toner cartridge products ONLY.
- Installing The upgrade may cause a non-Samsung toner cartridge to malfunction.
- Do not run your printer during the firmware update.(Do not have any print job)