

# Firmware Release Note

<b>Model: M456x Series</b>	<b>Date: 7-Mar-2019</b>
----------------------------	-------------------------

V5.00.03.01 FW addresses total of 5 issues.

- Major Changes

1. Fixed to support the GCP uses latest google specified certificates.
2. Fixed the Google Address Book issues
3. Fixed SMTP to work even when server supports only TLSv1.2
4. Fixed the WSD Install issue in Win10 for a specific version.
5. Fixed the Memory issue with mDNS

Please upgrade the FW with V5.00.03.01 if any one of the problems below need to be resolved.

Version	Category	TSP ID	Division	Change Description
<b>V5.00.03.01</b> (7-Mar-2019)	Problem	-	KOR	Fixed to support the GCP uses latest google specified certificates.
	Problem	-	KOR	Fixed SMTP to work even when server supports only TLSv1.2
	Problem	-	KOR	Fixed, when snmpcommunity.cgi is called SNMPv3 is getting disabled issue.
	Problem	-	KOR	Fixed the WSD Install issue in Win10 for a specific version.
	Problem	-	KOR	Fixed the Google Address Book issues.
	Problem	-	KOR	Fixed the Memory issue with mDNS.
	Problem	-	KOR	Fixed the issue of Box app Authentication.

## Software Component Versions

System Firmware	V5.00.03.01
Main FW Version	V11.01.00.03.01_190215
XOA Web	1.4.28
UP	1.17.29_(20170315110258)
Engine Firmware	V1.00.09_171205
File System Version	V22.00.00.00.12
Scanner Version	V3.00.00.18_170912
Fax Version	V3.02
Boot Rom Version	V22.10.00.00.23_190211
UI Firmware	V5.42.00.16.00_18101009
HCF/SCF version	V2.00.05
Scan_Control	V1.1
Samsung Mobile Print	V11.50_170710
PCL5E	V3.8.19_170720
PCLXL	V3.11.00.88_170309
PS/PDF/XPS	V3.6.23.01.62.02.06_170609

## Image Quality Tables

EP	V1.60
Fuser	V1.82
Toner	V1.70
TR	V1.30
Print CMS	M4560 PRINT V1.00.03.16
Copy CMS	V5.00.0628
Scan CMS	V0.71
Print IEM	V0.2
Copy IEM	V0.3

**Update dependency**

N/A
-----

**Solution Compatibility Table (M4560 : V5.00.03.01)**

Category	Solution Name	Solution Version	V5.00.03.01	Verified F/W Version
BCPS	CloudConnectorCore	2.50.006	○	V5.00.02
	DocumentWorkflowCore	2.50.006	○	V5.00.02
	PrintingSecurityCore	2.50.006	○	V5.00.02
	SecureLoginCore	2.50.006	○	V5.00.02
	UsageTrackerCore	2.50.006	○	V5.00.02
	XOA-WEB Enabler	2.00.003	○	V5.00.01.25
ISV-XOA-E	Equitrac	EQLogin_1.1.0.98.par ( Server : 5.2.21.8778 )	○	V5.00.01.25
	PaperCut	1.1.0 ( Server : 16.4 (build 38954))	○	V5.00.02
	PrintFleet Cloud Embedded DC	1.0.239 ( Server : 3.6)	○	V5.00.01.25
	SafeCom	010.24.21 ( Server : 10.52.7.2(S82070.520*07))	○	V5.00.01.25
	Scanshare Essentials	1.5.10.163 ( Server : 4.0.5)	○	V5.00.01.25
PrinterOn	PrinterOn Branded Agent	2.03.003	○	V5.00.02

- ◎ A solution has been verified and MUST be compatible with the releasing F/W version.
- Previously the supported solutions have been tested and verified with the version specified in the "Verified F/W version" row in the table. The required test has been conducted on this FW version to ensure the backward compatibility with "Verified F/W version".

**Release History**

Version	Category	TSP ID	Division	Change Description
V5.00.02 (7-Mar-2018)	Problem	-	KOR	Change to define start and end time when enabling performance optimization feature.
	Requirement	-	DEV	Add Google's root certificate for GCP.
	Problem	TP17801L	SEBN	Fixed an issue of the reset database menu being displayed at booting phase by intermittent corruption of audit database index.
	Problem	-	DEV	Fixed the issue of failing to activate license when only setting up SSL option without specifying SSL port at the license server address
V5.00.01 (13-Sep-2017)	First version	-	-	First release