

HP ScanJet Enterprise Flow 5000 s5

Firmware Readme

- Product Name: HP ScanJet Enterprise Pro 5000 s5
- Model Number: 6FW09A

Description:

- This document contains information for the firmware revision.
- Firmware Version: V0.57(0724y23)

Enhancements and Fixes provided with this Firmware Version

The following new functionality or features are provided by this firmware release: V0.57(0724y23)

Fix and enhancements

- Improved Firmware Update Tool

MD5 Checksum

- Exe file: 963f4fee3c3dcb17787f2e3f4101a6c4

Enhancements and Fixes provided with this Firmware Version

The following new functionality or features are provided by this firmware release: V0.57(1007y22)

Fix and enhancements

- Change Scan to USB drive default BW threshold value. (110 -> 170)

MD5 Checksum

- Exe file: 998ee9b758f7d3845b135e47bae6f812

Enhancements and Fixes provided with this Firmware Version

The following new functionality or features are provided by this firmware

release: V0.54

Fix and enhancements

- Fix WIA transfer fail issue related to WHQL

MD5 Checksum

- Exe file: e94973237ff17434a39789c6e1a3f2b1

Installation Instructions

- Through USB

- Download the flash firmware updater file from hp.com to the PC desktop
- Turn the scanner on
- Double click on the firmware update utility file (exe file)
- HP firmware update window will open (Command Prompt)
- Close window automatically when the FW update process is completed.