

Firmware Release Note

Model : SL-M4530ND, 4530NX	Date :	June 12, 2020
-----------------------------------	---------------	----------------------

Version	Category	Change Description
V3.00.01.07 (Jan-26,2015)	Fix Defect	PickUp jam problem when Tray switching from tray1 to option tray.
V3.00.01.18 (July-17,2015)	Fix Defect	[Google Cloud Print] Print & deregistration doesn't work properly
		Continuous printing large image from paper size, device is reset automatically.
		Fix Open Source issue
		[Netwrok job accounting] Does not Display User ID / Password Input Window When Setting the Job Accounting.
		[AirPrint] Modifications for AirPrint v1.4 certification.
		Menu Management menu is not available in SyncThru Web Service page
		IGPL Licence Issue Fix
		Paper type handling error
		Print job holds and not printing when paper mismatch occurs[manual continue]
V3.00.01.20 (Mar-20,2017)	Add Func.	B2B site requirement(borderless printing support)
		B2B site requirement(Best Buy PJJ paper setting)
		B2B site requirement(Support Universal size in MP tray)
		B2B site requirement(Support Lexmark Postscript UPD for BestBuy)
		B2B site requirement(Add Cloning Contents for Bestbuy)
		Implement 'Change Device Admin PW in FAP' Request
	Fix Defect	When printing with PS driver, last band image was missed
		Fix Secure job is not getting printed after reboot
		Fix Cloning issue
		Fix paper empty message is display even though tray isn't empty
		Fuser counter was not cleared when new fuser was installed.
V3.00.01.22 (Nov-29,2018)	Fix Defect	Fix the print quality(streak) issue.
		Fix the Google Cloud Print issue(Error Code : 11-1112)
V3.00.01.25 (May-25,2020)	Fix Defect	Network component update.
		Barcode printing functionality removed.


※ Note

- Please do not turn off the printer and your computer until firmware update finishes.
- If you are using USB connection, disconnect all other USB printers from the PC.
- The firmware update you are about to install has been tested for compatibility with Samsung toner cartridge products ONLY.
Installing The upgrade may cause a non-Samsung toner cartridge to malfunction.
- Do not run your printer during the firmware update.(Do not have any print job)

How to update the firmware using a USB cable.

1. Make sure that the machine is connected to the PC with a USB cable.
2. Menu > Admin Setup > Firmware Upgrade > ON
3. Drag the firmware file(*.hd) and Drop down it on usblist2.exe.

And then, firmware update will be started automatically.



4. The firmware update will start.
Once the firmware update is complete, the machine will be rebooted automatically.

Updating from the Network

1. Go to the SyncThruWeb Service (SWS) main home page.
Login as Admin in SyncThruWeb Service.
NOTE: Login using the Administrator ID and Password established during initial machine setup.
2. Click [Maintenance] on the top menu.
And then click [Firmware Upgrade] or Application Management > Application
3. Click Add button
4. Click [Browse]. Choose installation file by browsing file system. And click OK button
5. The uploading step will start. After this step, next step will be started automatically.
6. The firmware update will start.
7. Once the f/w update is complete, the machine power-off and power-on automatically.